

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2205545
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	5ZT2PUWB9S4023338
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	425 / 425
Labor rate:	\$115.00	ITEM #	PUT305BHCE-1
OWNER INFORMATION		DEALER RO #	11737B
		CLAIM START DATE	02/19/2025
		CLAIM END DATE	02/28/2025

Retail Date of Purchase	WARRANTY EXPIRATION DATE
-------------------------	--------------------------

Claim Line Details

Labor

Line# 1	Operation Code 30-95-24-00-000947 Complaint, Cause, Correction Original Note : greeneway@dealer-advisors.com, 2025-02-19 12:59:36 :: Complaint: Velcro strip not fully attached to the bench on the right side. Cause: Looks like Velcro broke away from screw. Correction: Need to screw back down.	Operational Description Dinette Cushions - Interior/Dinette/Repair/No Tread Code		
Model#		Dlr Sub Hrs	0.30	Sub Labor Amt \$34.50
Serial#		Appr Hrs	0.10	Appr Labor Amt \$11.50
Notes				

Submitted	Labor Amt	\$34.50	Approved	Labor Amt	\$11.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$34.50		Total	\$11.50

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	