

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 11751

Date In: 26 FEB 25 Author: MGRAY  
Promised Date: 04 JUL 25 Stock No: 11300  
: Year: 2025  
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER  
Address: 8220 STATE HWY 13 SOUT Brand: CEDAR CREEK EXPERIENCE  
: WISCONSIN RAPIDS, WI Model: 35RL  
Postal/Zip: 54494 Miles/Hrs: 0  
Phone#(res): 800-758-2272 Exterior Color:  
Phone#(bus): Unit Type: FW-FIFTH WHEEL  
Cell Phone: License#:  
Email: NONE Tag#: DB 2/28  
Purchased Date: 07 MAR 25 :  
Delivery Date: 04 JUL 25 :  
InService Date: :  
Serial#: 4X4FCRL2XSS234490 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
CEN COMPLAINT: CLEAN EXTERIOR- NEW I PDI PRE-D  
CAUSE: New unit  
CORRECTION: Washed and desalted  
NFWS COMPLAINT: NEW FIFTH WHEEL STOCK PREP I PDI PRE-D  
CAUSE: New unit  
CORRECTION: Done  
WS COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF I PDI PRE-D  
CONTAINED - TOWABLE  
CAUSE: New prep  
CORRECTION: Done  
WARR COMPLAINT: WARRANTY REPAIR 1 - When extending the W 1021 FORES  
foot rest of recliner it hits the slide  
fascia and begins pushing it off  
CAUSE: Mfg installed recliner too close to the  
wall  
CORRECTION: Removed the fascia so I could extend the  
foot rests on recliner assembly, beneath  
both recliners removed screws holding  
them in place , moved them over so the  
recliner arm does not hit the fascia  
.remove nails from the fascia board and  
reinstalled the fascia REQUESTING 1.50  
HOURS APPROVED  
WARR COMPLAINT: WARRANTY REPAIR 2 - bottom of bed panel W 1021 FORES  
has flaking chipped veneer  
CAUSE: Rough cut from mfg  
CORRECTION: Used wood marker to cover the peeled up  
edge REQUESTING .20 HOURS APPROVED

Continued on page 2

Work Order : 11751

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 3 -loose strings from      W    1021   FORES
        CAUSE:      FROM MFG Loose strings from carpet
        CORRECTION: Used scissors and cut away the loose
        strings REQUESTING .20 HOURS APPROVED
WARR    COMPLAINT:  WARRANTY REPAIR 4 - something stuck on      W    1021   FORES
        CAUSE:      FROM MFG Heavy duty glue on the fabric
        CORRECTION: Tried removing to no avail so note with
        mfg if future customer wants new fabric
        REQUESTING .10 HOURS APPROVED
WARR    COMPLAINT:  WARRANTY REPAIR 6 - bubble in lino in        W    1021   FORES
        CAUSE:      Flooring in bedroom has a bit of bubble
        in it FROM MFG
        CORRECTION: I would like noted with mfg if future
        customer has issue with this thank you
        REQUESTING .10 HOURS APPROVED
WARR    COMPLAINT:  WARRANTY REPAIR 7 - CHIPS IN THE BACK        W    1021   FORES
        CAUSE:      Chipped BACK SPLASH FROM MFG
        CORRECTION: Used wax crayons to cover and fill the
        areas REQUESTING .10 HOURS APPROVED
WARR    COMPLAINT:  WARRANTY REPAIR 8 - ON THE ISLAND IN THE W    1021   FORES
        CAUSE:      Gouged wood FROM MFG
        CORRECTION: Used water and heat gun to swell wood to
        even put the gouge on each door then
        used wood pen and crayons to blend both
        areas to the rest of the door REQUESTING
        .80 HOURS APPROVED
WARR    COMPLAINT:  WARRANTY REPAIR 9 - NOTING THAT THERE IS W    1021   FORES
        DAMAGED PANELLING BEHIND THE SLIDING
        BATHROOM DOOR ALONG WITH A GAP IN THE
        PANELLING
        CAUSE:      MFG
WARR    COMPLAINT:  WARRANTY REPAIR 10 - NOTING THE FRONT        W    1021   FORES
        CAP STORAGE COMPARTMENT HAS GAPS IN THE
        FRAME AND INNER PART OF THE COMPARTMENT
        CAUSE:      Mfg
        CORRECTION: Checked it out and I see nothing wrong I
        cannot screw screws in more it will
        cause frame to bend and door then will
        not fit correctly
WARR    COMPLAINT:  WARRANTY REPAIR 11 - THERE ARE SCREW        W    1021   FORES
        HOLES VISIBLE IN THE HIDDEN PANTRY DOOR

```

Continued on page 3

Work Order : 11751

CAUSE: NAIL HOLES FROM MFG INSTAL  
 CORRECTION: Filled with putty REQUESTING .10 HOURS  
 APPROVED

```
*****
Job # Part No      Description      PARTS    Bill to    Qty    Price    Total
*****
WS      071247312003 -50 ANTIFREEZE/ 1 GALLON I-PDI      0      7.55     0.00
*****
```

```
*****
Job#  Lab Code  Description      LABOUR    Mech Bill to    Hrs    Rate    Total
*****
  CEN CE      CLEAN EXTERIOR      HOD I-PDI      0.88    70.00    61.60
  NFWS RV1F-1A NEW STOCK PREP      HOD I-PDI      0.37    70.00    25.90
  WS W495     WINTERIZE RV (WATER SY HOD I-PDI      0.70    70.00    49.00
  NFWS RV1F-1A NEW STOCK PREP      HOD I-PDI      1.45    70.00   101.50
ARR01 Z992     MISC LABOUR CODE (WARR HOD W-1021    1.48   115.00   170.20
ARR02 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.20   115.00    23.00
ARR03 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.20   115.00    23.00
ARR04 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.10   115.00    11.50
  NFWS RV1F-1A NEW STOCK PREP      HOD I-PDI      0.10    70.00     7.00
ARR01 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.02   115.00     2.30
  NFWS RV1F-1A NEW STOCK PREP      HOD I-PDI      0.62    70.00   43.40
  NFWS RV1F-1A NEW STOCK PREP      HOD I-PDI      0.17    70.00   11.90
ARR06 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.10   115.00   11.50
  NFWS RV1F-1A NEW STOCK PREP      HOD I-PDI      1.79    70.00  125.30
ARR07 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.10   115.00   11.50
ARR08 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.80   115.00   92.00
ARR09 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.50   115.00   57.50
ARR10 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.50   115.00   57.50
ARR11 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.30   115.00   34.50
*****
```

```
*****
Job #  Excode  Description      EXTRAS    bill to    Qty    Price    Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL W-1021    1.00     0.00     0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I      PDI          0.00    425.60    0.00     0.00     0.00    425.60
W      1021         0.00    494.50    0.00     0.00     0.00    494.50

Totals          0.00    920.10    0.00     0.00     0.00    920.10
*****
```

&k2S  
&k0S