

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11751

Date In: 26 FEB 25 Author: MGRAY
Promised Date: 04 JUL 25 Stock No: 11300
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT Brand: CEDAR CREEK EXPERIENCE
: WISCONSIN RAPIDS, WI Model: 35RL
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: NONE Tag#: DB 2/28
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 4X4FCRL2XSS234490 :

Job # Description JOB INFORMATION Type Bill To

CEN COMPLAINT: CLEAN EXTERIOR- NEW I PDI PRE-D
CAUSE: New unit
CORRECTION: Washed and desalted
NFWS COMPLAINT: NEW FIFTH WHEEL STOCK PREP I PDI PRE-D
CAUSE: New unit
CORRECTION: Done
WS COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF I PDI PRE-D
CONTAINED - TOWABLE
CAUSE: New prep
CORRECTION: Done
WARR COMPLAINT: WARRANTY REPAIR 1 - When extending the W 1021 FORES
foot rest of recliner it hits the slide
fascia and begins pushing it off
CAUSE: Mfg installed recliner too close to the
wall
CORRECTION: Removed the fascia so I could extend the
foot rests on recliner assembly, beneath
both recliners removed screws holding
them in place , moved them over so the
recliner arm does not hit the fascia
.remove nails from the fascia board and
reinstalled the fascia REQUESTING 1.50
HOURS
WARR COMPLAINT: WARRANTY REPAIR 2 - bottom of bed panel W 1021 FORES
has flaking chipped veneer
CAUSE: Rough cut from mfg
CORRECTION: Used wood marker to cover the peeled up
edge REQUESTING .20 HOURS

Continued on page 2

Work Order : 11751

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 3 -loose strings from      W    1021   FORES
        CAUSE:      FROM MFG Loose strings from carpet
        CORRECTION: Used scissors and cut away the loose
        strings REQUESTING .20 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 4 - something stuck on      W    1021   FORES
        CAUSE:      FROM MFG Heavy duty glue on the fabric
        CORRECTION: Tried removing to no avail so note with
        mfg if future customer wants new fabric
        REQUESTING .10 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 6 - bubble in lino in        W    1021   FORES
        CAUSE:      repaired by mfg in linolium
        Flooring in bedroom has a bit of bubble
        in it FROM MFG
        CORRECTION: I would like noted with mfg if future
        customer has issue with this thank you
        REQUESTING .10 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 7 - CHIPS IN THE BACK        W    1021   FORES
        CAUSE:      Chipped BACK SPLASH FROM MFG
        CORRECTION: Used wax crayons to cover and fill the
        areas REQUESTING .10 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 8 - ON THE ISLAND IN THE W    1021   FORES
        KITCHEN THERE IS A CHIP IN BOTH THE
        CABINET DOORS THAT FACE THE DINNING ROOM
        TABLE
        CAUSE:      Gouged wood FROM MFG
        CORRECTION: Used water and heat gun to swell wood to
        even put the gouge on each door then
        used wood pen and crayons to blend both
        areas to the rest of the door REQUESTING
        .80 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 9 - NOTING THAT THERE IS W    1021   FORES
        DAMAGED PANELLING BEHIND THE SLIDING
        BATHROOM DOOR ALONG WITH A GAP IN THE
        PANELLING
        CAUSE:      MFG
WARR    COMPLAINT:  WARRANTY REPAIR 10 - NOTING THE FRONT        W    1021   FORES
        CAP STORAGE COMPARTMENT HAS GAPS IN THE
        FRAME AND INNER PART OF THE COMPARTMENT
        CAUSE:      Mfg
        CORRECTION: Checked it out and I see nothing wrong I
        cannot screw screws in more it will
        cause frame to bend and door then will
        not fit correctly
WARR    COMPLAINT:  WARRANTY REPAIR 11 - THERE ARE SCREW        W    1021   FORES
        HOLES VISIBLE IN THE HIDDEN PANTRY DOOR

```

Continued on page 3

Work Order : 11751

CAUSE: NAIL HOLES FROM MFG INSTAL
 CORRECTION: Filled with putty REQUESTING .10 HOURS

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
WS	071247312003	-50 ANTIFREEZE/	1 GALLON	I-PDI	0	7.55	0.00

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
CEN	CE	CLEAN EXTERIOR		HOD	I-PDI	0.88	70.00	61.60
NFWS	RV1F-1A	NEW STOCK PREP		HOD	I-PDI	0.37	70.00	25.90
WS	W495	WINTERIZE RV (WATER SY		HOD	I-PDI	0.70	70.00	49.00
NFWS	RV1F-1A	NEW STOCK PREP		HOD	I-PDI	1.45	70.00	101.50
ARR01	Z992	MISC LABOUR CODE (WARR		HOD	W-1021	0.48	115.00	55.20
ARR02	Z992	MISC LABOUR CODE (WARR		HOD	W-1021	0.50	115.00	57.50
ARR03	Z992	MISC LABOUR CODE (WARR		HOD	W-1021	0.50	115.00	57.50
ARR04	Z992	MISC LABOUR CODE (WARR		HOD	W-1021	0.50	115.00	57.50
NFWS	RV1F-1A	NEW STOCK PREP		HOD	I-PDI	0.10	70.00	7.00
ARR01	Z992	MISC LABOUR CODE (WARR		HOD	W-1021	0.02	115.00	2.30
NFWS	RV1F-1A	NEW STOCK PREP		HOD	I-PDI	0.62	70.00	43.40
NFWS	RV1F-1A	NEW STOCK PREP		HOD	I-PDI	0.17	70.00	11.90
ARR06	Z992	MISC LABOUR CODE (WARR		HOD	W-1021	0.50	115.00	57.50
NFWS	RV1F-1A	NEW STOCK PREP		HOD	I-PDI	1.79	70.00	125.30
ARR07	Z992	MISC LABOUR CODE (WARR		HOD	W-1021	0.50	115.00	57.50
ARR08	Z992	MISC LABOUR CODE (WARR		HOD	W-1021	0.50	115.00	57.50
ARR09	Z992	MISC LABOUR CODE (WARR		HOD	W-1021	0.50	115.00	57.50
ARR10	Z992	MISC LABOUR CODE (WARR		HOD	W-1021	0.50	115.00	57.50
ARR11	Z992	MISC LABOUR CODE (WARR		HOD	W-1021	0.50	115.00	57.50

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
ARR01	SSE	SHOP SUPPLIES -	EXTERNAL	W-1021	1.00	0.00	0.00

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	PDI	0.00	425.60	0.00	0.00	0.00	425.60
W	1021	0.00	575.00	0.00	0.00	0.00	575.00
Totals		0.00	1000.60	0.00	0.00	0.00	1,000.60

&k2S
 &k0S