

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11798B

Date In: 26 SEP 25 Author: MGRAY
Promised Date: 31 MAY 26 Stock No: 11356
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN
Address: 8220 STATE HWY 13 SOUT Brand: MOMENTUM MAV
: WISCONSIN RAPIDS, WI Model: 24MAV
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TTH-TT TOY HAULER
Cell Phone: License#:
Email: NONE Tag#: NOW SOLD TO FITZPATRIC
Purchased Date: 07 FEB 26 :
Delivery Date: 04 JUL 26 :
InService Date: :
Serial#: 573TM3029S1222451 :

```
*****  
Job # Description JOB INFORMATION Type Bill To  
*****  
WARR COMPLAINT: WARRANTY REPAIR 1 - the filter cap on W 1020 GRAND  
the suction side of the water pump is  
cracked in half  
CAUSE: The clear cover for the pump filter on  
the suction side cracked and was leaking  
water, i replaced the filter and housing  
CORRECTION: Done REQUEST .3  
WARR COMPLAINT: WARRANTY REPAIR 2 - the screws on the W 1020 GRAND  
bottom of both reliners are backing  
themselves out, both chairs are held on  
with 2 screws  
CAUSE: The screws on the bottom of both chairs  
came loose and fell out at some point  
and put in a drawer, i put locktight on  
them and put them back in, one screw is  
missing  
CORRECTION: Done REQUEST .6  
WARR COMPLAINT: WARRANTY REPAIR 3 - the farthest right W 1020 GRAND  
cabinet above the table is cracked.  
CAUSE: Cabinet door above dinette table has a  
flaw in it. The cabinet on the right  
side of the table is cracked and will  
need to be replaced.  
CORRECTION: Installed new cabinet door.  
WARR COMPLAINT: WARRANTY REPAIR 4 - the top drawer W 1020 GRAND  
between the stove and the fridge had a  
cut above the handle and a chip in the  
top left corner.
```

Continued on page 2

Work Order : 11798B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CAUSE:   Drawer front to the right of stove on
         top is damaged. The top drawer between
         the fridge and the stove has a 4 inch
         scratch in it as well as top left corner
         has a chipped corner, it will need to be
         replaced
CORRECTION: Installed new drawer front. .
WARR COMPLAINT: WARRANTY REPAIR 5 - the main door will   W   1020   GRAND
         not shut properly because the door lock
         catch is mouted upsidedown
CAUSE:   Entrance door adjustment for better
         closure.. I flipped the lock catch
         around and lowered it but the deadbolt
         will not go in, if i lower it any lower
         the holes will be exposed, we will need
         a new door
CORRECTION: Had to flip the striker plate around
         then use the lippert camber tool to take
         some of the camber out of the door.
WARR COMPLAINT: Transferred to GRV*11798C on 02 MAR 26   W   1020   GRAND
         Estimate amount was 0.00 WARRANTY REPAIR
         6 - The range hood vent cover is
         missing.
CAUSE:   The range hood vent cover got knocked
         off with ice and snow, put a new one on
CORRECTION: Done.

```

```

*****
Job # Part No      Description           PARTS   Bill to   Qty   Price   Total
*****
WARR0 752324009329 SHURFLO PUMP FILTER   W-1020   1   13.74   13.74
WARR0 146881         NOVAFLEX SEALANT BLACK W-1020   1   14.42   14.42
WARR0 822063613     DOOR CABINET 18 X 12 MOD W-1020   1   27.39   27.39
WARR0 822064376     DRAWER FRONT 8 X 15 1/2 W-1020   1   21.57   21.57
WARR0 8220561567   DOOR ENTRANCE 28 X 72 RH W-1020   1   769.87   769.87
WARR0 82201705     GLASS 1/8 X 14 1/2 X 8 1 W-1020   1   6.38    6.38
WARR0 161128       NOVAFLEX PRO 10 OZ TRANS W-1020   0   9.28    0.00
WARR0 82201118     BUTYL TAPE 1/8"X1"X30' B W-1020   0   14.82   0.00
WARR0 822070227     RANGE HOOD VENT, SHORT F W-1020   0   6.62    0.00
WARR0 82201705     GLASS 1/8 X 14 1/2 X 8 1 W-1020   1   6.38    6.38
WARR0 8220561567   DOOR ENTRANCE 28 X 72 RH W-1020   0   769.87   0.00

```

```

*****
Job# Lab Code Description   LABOUR   Mech Bill to   Hrs   Rate   Total
*****
ARR01 Z992   MISC LABOUR CODE (WARR EG   W-1020   0.00   140.00   0.00
ARR01 Z992   MISC LABOUR CODE (WARR EG   W-1020   0.30   140.00   42.00
ARR02 Z992   MISC LABOUR CODE (WARR EG   W-1020   0.60   140.00   84.00
ARR03 Z992   MISC LABOUR CODE (WARR EG   W-1020   0.50   140.00   70.00

```

Continued on page 3

Work Order : 11798B

```
*****
Job#  Lab Code  Description   LABOUR   Mech Bill to    Hrs    Rate    Total
*****
ARR03 RV32A-2    CABINET DOOR R&R RVDA  TD    W-1020    0.00   140.00    0.00
ARR04 Z992      MISC LABOUR CODE (WARR EG  W-1020    0.30   140.00   42.00
ARR04 RV32A-11  DRAWER BOX REPAIR RVDA  TD    W-1020    0.00   140.00    0.00
ARR05 Z992      MISC LABOUR CODE (WARR EG  W-1020    0.00   140.00    0.00
ARR05 O130      ENTRY DOOR ASSEMBLY, R TD  W-1020    1.00   140.00  140.00
ARR06 Z992      MISC LABOUR CODE (WARR EG  W-1020    0.00   140.00    0.00
ARR03 RV32A-2    CABINET DOOR R&R RVDA  TD    W-1020    0.00   140.00    0.00
*****
```

```
*****
Job #  Excode    Description   EXTRAS      bill to    Qty    Price    Total
*****
ARR05  FRT        FREIGHT                W-1020    0.00    0.00    0.00
ARR04  FRT        FREIGHT                W-1020    1.00   16.93   16.93
ARR06  SSE        SHOP SUPPLIES - EXTERNAL W-1020    0.00    0.00    0.00
ARR03  FRT        FREIGHT                W-1020    1.00   16.60   16.60
ARR03  FRT        FREIGHT                W-1020    1.00   19.61   19.61
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1020      859.75   378.00    0.00     53.14   0.00   1,290.89
*****
Totals      859.75   378.00    0.00     53.14   0.00   1,290.89
*****
```

&k2S
&k0S