

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11800B

Date In:	28 MAR 25	Author:	KOTT
Promised Date:	10 APR 25	Stock No:	11320
:	:	Year:	2025
Customer Name:	17067 - WESTRA, JEREMY	Manufacturer:	FOREST RIVER
Address:	N8657 STATE RD 73 N	Brand:	PUMA DESTINATION
:	RANDOPLH, WI	Model:	401RLFT
Postal/Zip:	53956	Miles/Hrs:	0
Phone#(res):	920-382-2996	Exterior Color:	
Phone#(bus):		Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:	JEREMY.WESTERA@WISCONS	Tag#:	del@st-4/10@9 DB: 3/3
Purchased Date:	18 JAN 25	:	:
Delivery Date:	10 APR 25	:	:
InService Date:		:	:
Serial#:	4X4TPUS2XSP105230	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 -the upper windows          W    1021    FORES
        have silicone smeared on them
        CAUSE:        Silicone smeared on windows at mfg
        CORRECTION:   Used quick solve then window cleaner to
        remove the smeared silicone REQUESTING
        .5 HOURS APPROVED .5
WARR    COMPLAINT:  WARRANTY REPAIR 2 - the 2 shades next to W    1021    FORES
        sofa the edges are curling at edges
        CAUSE:        Fabric not wide enough or heavy enough
        for the window size currently it's cut
        at 19" wide to still fit in valance 20"
        will work Need to order 2 new pull
        shades for unit current size 19" x 47"
        could go to 20" x 48" may hang better
        CORRECTION:   REQUESTING .6 HOURS FOR BOTH SHADES
        DENIED- FILE IS NOTED, THESE ARE THE
        SHADES INSTALLED
WARR    COMPLAINT:  WARRANTY REPAIR 3 -chip in wood                W    1021    FORES
        throughout unit
        CAUSE:        Chips
        CORRECTION:   I did these repairs while doing the
        excess putty on wood in unit REQUESTING
        .2 HOURS APPROVED .5
WARR    COMPLAINT:  WARRANTY REPAIR 4 - all the fascia on          W    1021    FORES
        sliderooms have smears of putty
        CAUSE:        Smeared putty from mfg
        CORRECTION:   I used Murphy's soap to wipe away putty
        on fascia ,trim,and doors then used a
```

Continued on page 2

Work Order : 11800B

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
                paint pen to cover any bare wood spots
                REQUESTING .8 HOURS APPROVED .8
WARR      COMPLAINT:  WARRANTY REPAIR 5 - the washer dryer      W      1021      FORES
                combo is not latched down to floor
                CAUSE:      Mfg did not add brackets to keep washer
                        in place
                CORRECTION: I added a strap to run across the front
                        of washer one to run across the front of
                        dryer was installed at mfg REQUESTING .2
                        HOURS DENIED- THEY DO NOT SECURE TO
                        FLOOR AT FACTORY

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 753962035152 TRAVEL SAFETY STRAPS      W-1021      1      5.62      5.62

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.49      140.00      68.60
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.01      140.00      1.40
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.50      140.00      70.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.50      140.00      70.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.50      140.00      70.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.50      140.00      70.00

```

```

*****
Job #  Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL      W-1021      1.00      0.00      0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      5.62      350.00      0.00      0.00      0.00      355.62
                Totals      5.62      350.00      0.00      0.00      0.00      355.62

```

&k2S
&k0S