

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 2257445
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TPUS2XSP105230
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 420 / 420
 ITEM # PUT401RLFT
 DEALER RO # 11800C
 CLAIM START DATE 04/08/2025
 CLAIM END DATE 04/10/2025

Labor rate: \$140.00

OWNER INFORMATION

JEREMY WESTRA
 N8657 STATE RD 73 N
 Randolph, WI 53956
 USA

Retail Date of Purchase 04/10/2025 WARRANTY EXPIRATION DATE 04/10/2026

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-103-01-00-001129 Floor Register - Interior/Flooring/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-04-08 14:29:36 :: Complaint: Floor vent in front of sofa is showing exposed wood. Cause: Manufacturing defect. Part of the vinyl curled out from under the vent.
 Correction: Need to shift the bent over to cover the exposed wood. Additional Note : greeneway@dealer-advisors.com, 2025-04-08 14:31:25 :: No labor code to repair/adjust vent cover.

Model# 1	Dlr Sub Hrs	0.20	Sub Labor Amt \$28.00
Serial# 1	Appr Hrs	0.20	Appr Labor Amt \$28.00

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 20-68-02-00-000696 Patio Door - Exterior/Patio Doors/Adjust/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-04-08 14:32:48 :: Complaint: Patio door has gap at top of the frame causing door to not close all the way. Cause: Manufacturing defect. The back roller is not in proper alignment. Correction: Need to adjust roller.

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$70.00
Serial#	Appr Hrs	0.50	Appr Labor Amt \$70.00

Notes

Labor

Line# 3 **Operation Code** **Operational Description**
 30-99-24-00-001030 Valance - Interior/Soft Goods/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-04-08 14:33:28 :: Complaint: Valance in bedroom is loose. Cause: Screws came loose. Correction: Will need to screw back down.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$28.00
Serial#	Appr Hrs	0.10	Appr Labor Amt \$14.00

Notes
 flat rate to secure

Submitted	Labor Amt	\$126.00	Approved	Labor Amt	\$112.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$126.00		Total	\$112.00

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.