

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11805B

Date In:	01 APR 25	Author:	KOTT
Promised Date:	08 APR 25	Stock No:	11309
:	:	Year:	2025
Customer Name:	50824 - WILSON, TIMOTH	Manufacturer:	GRAND DESIGN
Address:	2216 VALBERG DR	Brand:	IMAGINE XLS
:	STOUGHTON, WI	Model:	22MLE
Postal/Zip:	53589	Miles/Hrs:	0
Phone#(res):	715-210-5340	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	:	Tag#:	PU@ST-4/8@11
Purchased Date:	14 MAR 25	:	:
Delivery Date:	08 APR 25	:	:
InService Date:	:	:	:
Serial#:	573TE2624S3442454	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
DAF     COMPLAINT:  DAF-WARRANTY REPAIRS- 1.SLIDE FRAME          W    1020    GRAND
          SEEMS A LITTLE OFF 2.AWNING GOT STUCK
          FIRST TIME BRINGING OUT - PIECE OF
          PLASTIC FEEL FROM AWNING 3.GAP, IN
          PANELS ABOVE BED CABINETS 4.MAY NEED TO
          FIX A BATTEN STRIP OVER BY THE SINK IN
          KITCHEN 5.CENTER COUNSEL ON SOFA SEEMS
          LOOSE 6.SLIDE ROOM TIMING SEEMS OFF,
          COMES IN SPUTTERING.
          CAUSE:      Mfg daf
          CORRECTION: Each on own warranty line
WARR    COMPLAINT:  WARRANTY REPAIR 1 - TIMING ON THE SLIDE    W    1020    GRAND
          SEEMS OFF. SPUTTERS WHEN BRING SLIDE IN
          CAUSE:      This is the chain driven type this is
                      how they operate NPF
          CORRECTION: NPF
WARR    COMPLAINT:  WARRANTY REPAIR 2 - AWNING WAS STUCK      W    1020    GRAND
          WHEN TRYING TO BRING IT OUT. HAD TO
          MANUALLY MOVE BOTH ARMS IN ORDER TO GET
          IT EXTENDED OUT. ALSO A PIECE OF PLASTIC
          FELL OFF THE RIGHT ARM
          CAUSE:      This is a new style need to go flip the
                      handles on inner arms to release NPF
                      The black plastic fell out that covers
                      the electric wire
          CORRECTION: Reinstalled the plastic
WARR    COMPLAINT:  WARRANTY REPAIR 3 - THERE IS A GAP IN      W    1020    GRAND
          THE CEILING PANELLING ABOVE THE
```

Continued on page 2

Work Order : 11805B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                CUPBOARDS THAT IS LOCATED ABOVE THE BED
CAUSE:      Mfg
CORRECTION: This is how unit is built nothing I can
            do to repair , it does not look as bad
            in real time as the pic so after unit
            warms up it may have taken the small gap
            away
WARR    COMPLAINT:  WARRANTY REPAIR 4 - BATTEN STRIP IN THE  W    1020    GRAND
            CORNER OF THE KITCHEN BEHIND THE SINK
            LOOKS TO BE EITHER PERTUDING/PULLING
            AWAY. NEED TO LOOK AT
CAUSE:      Mfg
CORRECTION: Npf
WARR    COMPLAINT:  WARRANTY REPAIR 5 - CENTER CONSOLE ON    W    1020    GRAND
            THE SOFA SEEMS REALLY LOOSE. CAN BE
            FREELY MOVED LEFT TO RIGHT
CAUSE:      Broken Order new center piece for
            recliners.. pics taken of center piece
            and the tag on it
CORRECTION: REQUESTING 1 HOUR

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
DAF Z991      DAF-WARRANTY REPAIR    HOD  W-1020      0.10   115.00   11.50
ARR01 Z992    MISC LABOUR CODE (WARR HOD  W-1020      0.50   115.00   57.50
ARR02 Z992    MISC LABOUR CODE (WARR HOD  W-1020      0.50   115.00   57.50
ARR03 Z992    MISC LABOUR CODE (WARR HOD  W-1020      0.50   115.00   57.50
ARR04 Z992    MISC LABOUR CODE (WARR HOD  W-1020      0.50   115.00   57.50
ARR05 Z992    MISC LABOUR CODE (WARR HOD  W-1020      0.41   115.00   47.15
ARR05 Z992    MISC LABOUR CODE (WARR HOD  W-1020      0.09   115.00   10.35

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1020        0.00     299.00     0.00     0.00     0.00     299.00
Totals            0.00     299.00     0.00     0.00     0.00     299.00

```

&k2S
&k0S