

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 11814B

Date In: 04 APR 25 Author: KOTT  
Promised Date: 25 DEC 25 Stock No: 11321  
: Year: 2025  
Customer Name: 17590 - FAUGHT, JASON Manufacturer: GRAND DESIGN  
Address: N1708 6TH AVENUE PO BO Brand: MOMENTUM G-CLASS  
: COLOMA, WI Model: 415G  
Postal/Zip: 54930 Miles/Hrs: 0  
Phone#(res): 9204206815 Exterior Color:  
Phone#(bus): Unit Type: FWH-FW TOY HAULER  
Cell Phone: License#:  
Email: HAPPYHOURS4@HOTMAIL.CO Tag#:  
Purchased Date: 14 JAN 25 :  
Delivery Date: 14 APR 25 :  
InService Date: :  
Serial#: 573FM4731SBB03873 :

```
*****
Job # Description JOB INFORMATION Type Bill To
*****
WARR COMPLAINT: WARRANTY REPAIR 1 - Vent fan control W 1020 GRAND
dropped out of ohc bottom panel in
kitchen
CAUSE: One screw was not drilled into the panel
CORRECTION: Reinstalled both screws now both are
screwed into panel REQUESTING .1
APPROVED .3
WARR COMPLAINT: WARRANTY REPAIR 2 -Kitchen faucet does W 1020 GRAND
not retract as it should
CAUSE: Subpar product weight
CORRECTION: Does not matter where weight is put on
the line it does not retract the hose
back up WILL NEED TO REPLACE THE FAUCET
REQUESTING .5 APPROVED
WARR COMPLAINT: WARRANTY REPAIR 4 - On the walls W 1020 GRAND
throughout the unit there are smudges
and dirt marks
CAUSE: Mfg
CORRECTION: Used Murphy's oil soap to clean off
spots on the wall REQUESTING .2 DENIED,
PART OF PDI
WARR COMPLAINT: WARRANTY REPAIR 5 -The door to bedroom W 1020 GRAND
is not lying flush itdoes open and
close properly and you only see the door
not lying flush from the bedroom side
CAUSE: Mfg
CORRECTION: I added a couple nails to the top of
```

Continued on page 2

Work Order : 11814B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
doorway trim to help with the door
looking uneven it opens and closes as it
should so that's all I can do as far as
it looking uneven REQUESTING .1 APPROVED
.3
WARR    COMPLAINT:  WARRANTY REPAIR 3 - Ceiling in garage      W      1020    GRAND
has a black mark and in hall up near
bathroom there are some smudges on the
ceiling
CAUSE:      Mfg in the unit
CORRECTION: used cleaner and quick solve to remove
black marks and I cleaned all white trim
strips on ceiling throughout unit they
had a scrape in center on all 9 ceiling
trim REQUESTING .5 APPROVED .2
WARR    COMPLAINT:  WARRANTY REPAIR 6 -The bedrooms          W      1020    GRAND
headboard looks off kilter
CAUSE:      Mfg installed it cockeyed
CORRECTION: Removed the screws and adjusted the
headboard this took awhile it's a pain
holding leveling REQUESTING 1 HOUR
DENIED, NO DEFECT SEEN
WARR    COMPLAINT:  WARRANTY REPAIR 8 -Base of toilet has      W      1020    GRAND
something coming from beneath it
CAUSE:      Debris left by mfg
CORRECTION: I carefully cut away the debris
REQUESTING .1 APPROVED .2
WARR    COMPLAINT:  WARRANTY REPAIR 9 - the lino and garage     W      1020    GRAND
floor have putty and a sticky substance
ground in to it
CAUSE:      Mfg
CORRECTION: I used quick solve DND a brush to remove
the putty and silicone that was ground
in REQUESTING .6 DENIED, PART OF PDI

```

```

*****
Job # Part No Description          PARTS          Bill to Qty Price Total
*****
WARR0 8220359 FAUCET KITCHEN SS GOOSENECK P W-1020 1 80.43 80.43

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.50 140.00 70.00
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.50 140.00 70.00
ARR04 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.50 140.00 70.00
ARR05 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.50 140.00 70.00
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.12 140.00 16.80
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.38 140.00 53.20

```

Continued on page 3

Work Order : 11814B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.00   140.00    0.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.50   140.00   70.00
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.50   140.00   70.00
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.50   140.00   70.00
*****
```

```
*****
Job #  Excode    Description  EXTRAS  bill to    Qty    Price    Total
*****
ARR01  SSE        SHOP SUPPLIES - EXTERNAL  W-1020    1.00    0.00    0.00
ARR02  FRT        FREIGHT FOR JOB 2        W-1020    1.00   14.19   14.19
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1020          80.43    560.00    0.00     14.19    0.00    654.62
*****
Totals          80.43    560.00    0.00     14.19    0.00    654.62
*****
```

&k2S  
&k0S