

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11814B

Date In: 04 APR 25 Author: KOTT
Promised Date: 25 DEC 25 Stock No: 11321
: Year: 2025
Customer Name: 17590 - FAUGHT, JASON Manufacturer: GRAND DESIGN
Address: N1708 6TH AVENUE PO BO Brand: MOMENTUM G-CLASS
: COLOMA, WI Model: 415G
Postal/Zip: 54930 Miles/Hrs: 0
Phone#(res): 9204206815 Exterior Color:
Phone#(bus): Unit Type: FWH-FW TOY HAULER
Cell Phone: License#:
Email: HAPPYHOURS4@HOTMAIL.CO Tag#:
Purchased Date: 14 JAN 25 :
Delivery Date: 14 APR 25 :
InService Date: :
Serial#: 573FM4731SBB03873 :

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT: WARRANTY REPAIR 1 - Vent fan control dropped out of ohc bottom panel in kitchen CAUSE: One screw was not drilled into the panel CORRECTION: Reinstalled both screws now both are screwed into panel REQUESTING .1		W	1020 GRAND
WARR	COMPLAINT: WARRANTY REPAIR 2 -Kitchen faucet does not retract as it should CAUSE: Subpar product weight CORRECTION: Does not matter where weight is put on the line it does not retract the hose back up WILL NEED TO REPLACE THE FAUCET REQUESTING .5		W	1020 GRAND
WARR	COMPLAINT: WARRANTY REPAIR 4 - On the walls throughout the unit there are smudges and dirt marks CAUSE: Mfg CORRECTION: Used Murphy's oil soap to clean off spots on the wall REQUESTING .2		W	1020 GRAND
WARR	COMPLAINT: WARRANTY REPAIR 5 -The door to bedroom is not lying flush it does open and close properly and you only see the door not lying flush from the bedroom side CAUSE: Mfg CORRECTION: I added a couple nails to the top of doorway trim to help with the door looking uneven it opens and closes as it		W	1020 GRAND

Continued on page 2

Work Order : 11814B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                should so that's all I can do as far as
                it looking uneven REQUESTING .1
WARR    COMPLAINT:  WARRANTY REPAIR 3 - Ceiling in garage   W    1020   GRAND
                has a black mark and in hall up near
                bathroom there are some smudges on the
                ceiling
                CAUSE:      Mfg in the unit
                CORRECTION: used cleaner and quick solve to remove
                black marks and I cleaned all white trim
                strips on ceiling throughout unit they
                had a scrape in center on all 9 ceiling
                trim REQUESTING .5
WARR    COMPLAINT:  WARRANTY REPAIR 6 -The bedrooms       W    1020   GRAND
                headboard looks off kilter
                CAUSE:      Mfg installed it cockeyed
                CORRECTION: Removed the screws and adjusted the
                headboard this took awhile it's a pain
                holding leveling REQUESTING 1 HOUR
WARR    COMPLAINT:  WARRANTY REPAIR 8 -Base of toilet has   W    1020   GRAND
                something coming from beneath it
                CAUSE:      Debris left by mfg
                CORRECTION: I carefully cut away the debris
                REQUESTING .1
WARR    COMPLAINT:  WARRANTY REPAIR 9 - the lino and garage W    1020   GRAND
                floor have putty and a sticky substance
                ground in to it
                CAUSE:      Mfg
                CORRECTION: I used quick solve DND a brush to remove
                the putty and silicone that was ground
                in REQUESTING .6
    
```

```

*****
Job # Part No Description      PARTS           Bill to   Qty    Price    Total
*****
WARR0 8220359 FAUCET KITCHEN SS GOOSENECK P W-1020      0      80.43    0.00
    
```

```

*****
Job# Lab Code Description      LABOUR    Mech Bill to      Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50   140.00   70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50   140.00   70.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50   140.00   70.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50   140.00   70.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.12   140.00   16.80
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.38   140.00   53.20
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.00   140.00    0.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50   140.00   70.00
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50   140.00   70.00
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50   140.00   70.00
    
```

Continued on page 3

Work Order : 11814B

```
*****
Job #  Excode   Description  EXTRAS      bill to    Qty   Price   Total
*****
ARR01  SSE       SHOP SUPPLIES - EXTERNAL  W-1020    1.00   0.00    0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1020          0.00    560.00    0.00     0.00    0.00    560.00
      Totals          0.00    560.00    0.00     0.00    0.00    560.00
*****
```

&k2S
&k0S