

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11839

Date In: 31 MAR 25 Author: KOTT
Promised Date: 25 DEC 25 Stock No: 11277
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN
Address: 8220 STATE HWY 13 SOUT Brand: TRANSCEND
: WISCONSIN RAPIDS, WI Model: 335BHT
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#:
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573TT372XS8838403 :

Job # Description JOB INFORMATION Type Bill To

PDIT COMPLAINT: NEW STOCK PREP I PDI PRE-D
CAUSE: Sold
CORRECTION: Done filled up and I stalled battery
WARR COMPLAINT: WARRANTY REPAIR 1 - Door to bunk room W 1020 GRAND
needs adjusting and the magnet catch
needs to be moved
CAUSE: Misaligned door and the magnet catch not
installed in correct area
CORRECTION: Removed magnet ,removed the header to
have access to the rolling glides on top
of door adjusted the glides the door is
now closing evenly reinstalled the
header installed magnet so door now
catches I then cleaned up and filled the
old holes in door trim REQUESTING .7
WARR COMPLAINT: WARRANTY REPAIR 2 - Main Bedrooms bottom W 1020 GRAND
left drawer has a scratch on the face of
it
CAUSE: Scratched
CORRECTION: Used wood crayon to cover the scratch
REQUESTING .2
WARR COMPLAINT: WARRANTY REPAIR 3 -Main bedrooms slider W 1020 GRAND
door has missing finish at the bottom
CAUSE: Mfg ding with missing finish at bottom
of the door
CORRECTION: I used wood marker then crayon to fell
in and blend REQUESTING .2
WARR COMPLAINT: WARRANTY REPAIR 4 -Valance in main W 1020 GRAND

Continued on page 2

Work Order : 11839

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                bedroom the top edge closest to the
                entry door has missing finish
        CAUSE:      Gouged at bottom peeling up finish
        CORRECTION: Used a marker and crayon to fill looks
                better but want noted in case customer
                not satisfied REQUESTING .3
WARR    COMPLAINT:  WARRANTY REPAIR 6 - bunk track for door W    1020    GRAND
                is bent the door gets hung up on bent
                track
        CAUSE:      Bent from mfg
        CORRECTION: Used pliers to carefully unbend the
                track door glides smooth now as it
                should REQUESTING .2
WARR    COMPLAINT:  WARRANTY REPAIR 7 - the white ceiling W    1020    GRAND
                trim has marks on it through our unit
        CAUSE:      Mfg
        CORRECTION: Cleaned with quick solve REQUESTING .4
WS       COMPLAINT:  WINTERIZE WATER SYSTEM & TRAPS -SELF I    PDI    PRE-D
                CONTAINED - TOWABLE
        CAUSE:      Sold
        CORRECTION: Done
WARR    COMPLAINT:  WARRANTY REPAIR 8 - huge scratch in lino W    1020    GRAND
                in main area cut right through
        CAUSE:      Mfg
        CORRECTION: Took pics of lino scratch REQUESTING
                GRAND DESIGN PICK UP THIS UNIT AND DO
                THE REPAIRS

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
PDITT 840821034507 12V 24 MDP BATTERY      I-PDI      1      85.20      85.20
PDITT 146508        BATTERY BOX GROUP 24      I-PDI      1      8.84      8.84
WS     071247312003 -50 ANTIFREEZE/ 1 GALLON I-PDI      3      7.55      22.65

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to      Hrs      Rate      Total
*****
PDITT RV1F-3B   SOLD FINISH PREP TRAVE HOD I-PDI      2.40      70.00      168.00
ARR01 Z992     MISC LABOUR CODE (WARR HOD W-1020      0.50      140.00      70.00
ARR02 Z992     MISC LABOUR CODE (WARR HOD W-1020      0.50      140.00      70.00
ARR03 Z992     MISC LABOUR CODE (WARR HOD W-1020      0.50      140.00      70.00
ARR04 Z992     MISC LABOUR CODE (WARR HOD W-1020      0.50      140.00      70.00
ARR06 Z992     MISC LABOUR CODE (WARR HOD W-1020      0.50      140.00      70.00
ARR07 Z992     MISC LABOUR CODE (WARR HOD W-1020      0.50      140.00      70.00
WS W495        WINTERIZE RV (WATER SY HOD I-PDI      0.66      70.00      46.20
PDITT RV1F-3B   SOLD FINISH PREP TRAVE HOD I-PDI      2.01      70.00      140.70
PDITT RV1F-3B   SOLD FINISH PREP TRAVE HOD I-PDI      0.09      70.00      6.30
WS W495        WINTERIZE RV (WATER SY HOD I-PDI      0.04      70.00      2.80

```

Continued on page 3

Work Order : 11839

```
*****
Job#  Lab Code  Description   LABOUR   Mech Bill to    Hrs    Rate    Total
*****
ARR08 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.50   140.00   70.00
*****
```

```
*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
PDITT  LP        PROPANE              I-PDI     60.00    0.74    44.40
ARR01  SSE        SHOP SUPPLIES - EXTERNAL  W-1020    1.00    0.00    0.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I      PDI          116.69      364.00      0.00      44.40      0.00      525.09
W      1020          0.00      490.00      0.00      0.00      0.00      490.00

Totals          116.69      854.00      0.00      44.40      0.00      1,015.09
*****
```

&k2S
&k0S