

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11851B

Date In:	07 APR 25	Author:	KOTT
Promised Date:	23 APR 25	Stock No:	11329
:	:	Year:	2025
Customer Name:	17616 - DOUCETTE, BOBB	Manufacturer:	FOREST RIVER
Address:	:	Brand:	PUMA DESTINATION
:	:	Model:	38RLB
Postal/Zip:	53237	Miles/Hrs:	0
Phone#(res):	9208501187	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	bobbiejdou@gmail.com	Tag#:	ST: 4/23@2DEL:5/2
Purchased Date:	12 FEB 25	:	:
Delivery Date:	23 APR 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPUP2XSP105530	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 -Marks on floor            W    1021    FORES
        covering
        CAUSE:          Stains on flooring
        CORRECTION:     Cleaned with quick solve  REQUESTING .3
WARR    COMPLAINT:  WARRANTY REPAIR 2 - walls have black        W    1021    FORES
        marks where the dining chairs rubbed up
        against
        CAUSE:          Marks on the walls
        CORRECTION:     Used Murphy's oil soap to remove without
        removing panels finish REQUESTING .2
WARR    COMPLAINT:  WARRANTY REPAIR 3 - right bunk hold is      W    1021    FORES
        not installed accurately it does not
        push in far enough to hold bunk up
        CAUSE:          Mfg
        CORRECTION:     Removed the plate on wall and then
        reinstalled it a bit forward then
        drilled the hole bigger now both latches
        work as they should bunk stays up as it
        should REQUESTING .5
WARR    COMPLAINT:  WARRANTY REPAIR 4 - fire extinguisher      W    1021    FORES
        strap is broken
        CAUSE:          Broken strap on fire extinguisher
        CORRECTION:     Removed and installed new extinguisher
        bracket only replaced REQUESTING .5
WARR    COMPLAINT:  WARRANTY REPAIR 5 - trim in corner of      W    1021    FORES
        bunk room is loose
        CAUSE:          Loose trim
        CORRECTION:     Used pin nailer to nail back into place
```

Continued on page 2

Work Order : 11851B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                REQUESTING .2
WARR    COMPLAINT:  WARRANTY REPAIR 6 -scrapes in the wood    W    1021    FORES
                                in different areas of the unit
                                CAUSE:      Mfg
                                CORRECTION:  Used wood pen to cover scratches then
                                                used Murphy's oil soap to remove smear
                                                marks REQUESTING .6
WARR    COMPLAINT:  WARRANTY REPAIR 7 - floor covering has    W    1021    FORES
                                missing color in some areas
                                CAUSE:      Missing color from mdg
                                CORRECTION:  First tried cleaning the spots but the
                                                fabrics color is actually missing I then
                                                used a paint pen to dab the areas to
                                                blend looks consistent now on all 3
                                                floor coverings REQUESTING .3

```

```

*****
Job # Part No   Description          PARTS          Bill to   Qty    Price    Total
*****
WARR0 822020147 FIRE EXTUNGUISHER BRACKET O W-1021      1     13.51    13.51

```

```

*****
Job#  Lab Code  Description          LABOUR    Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.30   140.00   42.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.20   140.00   28.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.29   140.00   40.60
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.21   140.00   29.40
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.06   140.00    8.40
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.34   140.00   47.60
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.20   140.00   28.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.60   140.00   84.00
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.20   140.00   28.00

```

```

*****
Job #  Excode    Description          EXTRAS          bill to    Qty    Price    Total
*****
ARR01  SSE       SHOP SUPPLIES - EXTERNAL  W-1021      1.00    0.00    0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id          Parts    Labour    Sublet    Extras    Tax    Total
*****
W    1021             13.51    336.00    0.00     0.00     0.00    349.51

                                Totals      13.51    336.00    0.00     0.00     0.00    349.51

```

Continued on page 3

Work Order : 11851B

&k2S
&k0S