

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 11862B

Date In: 27 AUG 25 Author: MGRAY  
Promised Date: 31 DEC 26 Stock No: 11330  
: Year: 2025  
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER  
Address: 8220 STATE HWY 13 SOUT Brand: PUMA CAMPING EDITION  
: WISCONSIN RAPIDS, WI Model: 305BHCE  
Postal/Zip: 54494 Miles/Hrs: 0  
Phone#(res): 800-758-2272 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: NONE Tag#: DB: 9/4  
Purchased Date: :  
Delivery Date: :  
InService Date: :  
Serial#: 5ZT2PUWBXS4023994 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
DAF COMPLAINT: DAF-WARRANTY REPAIRS- 1. ODS SLIDE DECAL W 1021 FORES  
LOOKS LIKE IT IS BUBBLING AND DECAL ON  
DS DOES TOO 2. SILICONE THROUGHOUT  
EXTERIOR 3.SILICONE GLOBS THROUGHOUT  
EXTERIOR 4.BEDROOM DOOR HAS PAINT  
CHIPPING 5.BUNKROOM BUNK CORNERS NEED  
TO BE SMOOTHED OUT  
CAUSE: Several decals on both sides are  
bubbleing and will need to be replaced,  
the bunk beds had some fraying wood on  
the corners i cut away the stuff  
sticking up and puttyed it, the main  
bedroom door closest to the front door  
was hanging loose because the screws  
pulled out of the door, i moved the  
bracket slightly and adjuster it.  
CORRECTION: Done.  
WARR COMPLAINT: WARRANTY REPAIR 1 -The tank fill probes W 1021 FORES  
are not grounded to the frame and will  
not read.  
CAUSE: Tank probes werent reading, they we not  
grounded properly. I added a ground wire  
to the frame.  
CORRECTION: Done. REQUEST: .75 HOURS OF LABOR  
WARRANTY AUTH: .75  
1 COMPLAINT: Several decals on both sides are W 1021 FORES  
bubbleing  
CAUSE: bubbles in decals on exterior unit

Continued on page 2

Work Order : 11862B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: replaced the decals on unit that was
              needed the other i had used a pin and
              work bubbles out    will need to be
              replaced- request 7 hours of labor
              (.50 hours per decal)  WARRANTY AUTH: 9
              HOURS OF LABOR
2  COMPLAINT: the bunk beds had some fraying wood on  W    1021  FORES
              the corners i cut away the stuff
              sticking up and puttied it
CAUSE:      FROM MFG- UNSURE AS TO WHY IT WAS
              FRAYING
CORRECTION: i cut away the stuff sticking up and
              puttied it  REQUEST .30 HOURS OF LABOR
              WARRANTY AUTH: .30 HOURS
3  COMPLAINT: the main bedroom door closest to the  W    1021  FORES
              front door was hanging loose
CAUSE:      the screws pulled out of the door
CORRECTION: i moved the bracket slightly and
              adjuster it. REQUEST .30 HOURS OF LABOR
              WARRANTY AUTH: .30 HOURS
4  Transferred to GRV*11862C on 18 FEB 26 Estimate  E    1000  GREEN
              amount was 0.00 needs decals for front cap are
              peeling

```

```

*****
Job # Part No  Description          PARTS      Bill to  Qty   Price   Total
*****
1      8220665271 DECAL, PUMA, SIDE DIE CUT  W-1021    1    20.32   20.32
1      82205272  DECAL, PUMA, SIDE DIE CUT  W-1021    1    20.32   20.32
1      822065244  DECAL, PUMA, SIDE DIE CUT  W-1021    1     8.62    8.62
1      822065270  DECAL, PUMA, SIDE DIE CUT  W-1021    1     8.62    8.62
1      822065284  DECAL, PUMA, SIDE DIE CUT  W-1021    1    15.05   15.05
1      822065290  DECAL, PUMA, SIDE DIE CUT  W-1021    1    15.05   15.05
1      822065280  DECAL, PUMA, SIDE DIE CUT  W-1021    1     3.60    3.60
1      822065281  DECAL, PUMA, SIDE DIE CUT  W-1021    1     3.60    3.60
1      822065282  DECAL, PUMA, SIDE DIE CUT  W-1021    1     3.39    3.39
1      822065283  DECAL, PUMA, SIDE DIE CUT  W-1021    1     3.39    3.39
1      822065278  DECAL, PUMA, SIDE DIE CUT  W-1021    1    12.91   12.91
1      822065279  DECAL, PUMA, SIDE DIE CUT  W-1021    1    12.91   12.91
1      822065293  DECAL, PUMA, DIE CUT #20-L W-1021    1     4.13    4.13
1      822065294  DECAL, PUMA, DIE CUT #20-R W-1021    1     4.13    4.13
1      822065244  DECAL, PUMA, SIDE DIE CUT  W-1021    1     8.62    8.62
1      822065270  DECAL, PUMA, SIDE DIE CUT  W-1021    1     8.62    8.62

```

```

*****
Job# Lab Code  Description          LABOUR    Mech Bill to  Hrs   Rate   Total
*****
  DAF Z991      DAF-WARRANTY REPAIR    EG    W-1021    0.10  140.00  14.00
ARR01 Z992      MISC LABOUR CODE (WARR EG    W-1021    0.35  140.00  49.00

```

Continued on page 3

Work Order : 11862B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR EG  W-1021    0.40   140.00   56.00
     2 WARR      MANUFACTURER WARRANTY EG  W-1021    0.30   140.00   42.00
     3 WARR      MANUFACTURER WARRANTY EG  W-1021    0.30   140.00   42.00
     1 WARR      MANUFACTURER WARRANTY JS  W-1021    3.78   140.00  529.20
     1 WARR      MANUFACTURER WARRANTY JS  W-1021    1.06   140.00  148.40
     1 WARR      MANUFACTURER WARRANTY JS  W-1021    1.37   140.00  191.80
     1 WARR      MANUFACTURER WARRANTY JS  W-1021    0.79   140.00  110.60
*****
```

```
*****
Job #  Excode    Description  EXTRAS      bill to    Qty    Price    Total
*****
ARR01  SSE        SHOP SUPPLIES - EXTERNAL W-1021    1.00    0.00    0.00
     1  FRT        FREIGHT FOR JOB 1 DECALS W-1021    1.00   39.24   39.24
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1021          153.28   1183.00    0.00    39.24    0.00   1,375.52
      Totals          153.28   1183.00    0.00    39.24    0.00   1,375.52
*****
```

&k2S  
&k0S