

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2583117
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	5ZT2PUVB7S4023968
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	425 / 425
Labor rate:	\$140.00	ITEM #	PUT304BHCE-1
OWNER INFORMATION		DEALER RO #	11865B
		CLAIM START DATE	02/17/2026
		CLAIM END DATE	02/17/2026
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor			
Line# 1	Operation Code 20-43-01-00-000589	Operational Description Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code	
	Complaint, Cause, Correction Original Note : greeneway@dealer-advisors.com, 2026-02-17 14:53:49 :: Complaint: There are bubbles in most of the decals on DS, rear and ODS. Cause: Decals are bubbling. Correction: Went around and popped and smoothed out the ones I could, the ODS gold decal to the left of the window will have to be replaced as the bubbles keep forming after popping. Additional Note : greeneway@dealer-advisors.com, 2026-02-17 14:54:31 :: Previous PA 2406262 expired- work is now done.		
Model#	Dlr Sub Hrs	1.00	Sub Labor Amt \$140.00
Serial#	Appr Hrs	1.00	Appr Labor Amt \$140.00
	Notes per expired claim 2406262		

Line# 2	Item #		Description			
	F100665278		DECAL, PUMA, SIDE DIE CUT #11-LH FR-24-91950A-LH			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$12.91	Sub Freight	\$18.78
	Appr Qty	1.00	Appr Dlr Price	\$12.91	Appr Freight	\$18.78
	Notes					

Line# 2	Operation Code 40-112-01-11-001353	Operational Description Tank Sensor - Probe Pods, each - Electrical/Monitor Panel/Replace/Electrical		
	Complaint, Cause, Correction Original Note : greeneway@dealer-advisors.com, 2026-02-17 14:54:48 :: Complaint: The tank levels are not showing up on the monitor panel. Cause: Tank probes were not grounded out properly from the manufacturer. Correction: Attached a cable to the frame to ground it out. Additional Note : greeneway@dealer-advisors.com 2026-02-17 14:56:07 :: Previous PA 2406262 expired- work is now done.			
Model#	Dlr Sub Hrs	0.70	Sub Labor Amt	\$98.00
Serial#	Appr Hrs	0.70	Appr Labor Amt	\$98.00
Notes per expired claim 2406262				

Line#	Operation Code	Operational Description
3	60-138-24-00-001519	Grey Water Tank (Read Notes!!!) - Plumbing/Drainage System/Repair/No Tread Code
	Complaint, Cause, Correction	

Original Note : greeneway@dealer-advisors.com, 2026-02-17 14:55:28 :: Complaint: Gray tank drain tube is leaking at a connection. Cause: A connection on the gray tank drain hose was leaking. Correction: Put ABS cement over it and it is no longer leaking. Additional Note : greeneway@dealer-advisors.com, 2026-02-17 14:56:13 :: Previous PA 2406262 expired- work is now done.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$42.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$42.00
Notes				

Submitted	Labor Amt	\$280.00	Approved	Labor Amt	\$280.00
	Parts & Freight	\$31.69		Parts & Freight	\$31.69
	Total	\$311.69		Total	\$311.69

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.