

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11878B

Date In: 24 APR 25 Author: KOTT
Promised Date: 25 DEC 25 Stock No: 11319
: Year: 2025
Customer Name: 17594 - TRENT, JOHN Manufacturer: FOREST RIVER
Address: W9480 COUNTY RD S Brand: FLAGSTAFF CLASSIC FW
: NEW LONDON, WI Model: 374DBH
Postal/Zip: 54961 Miles/Hrs: 0
Phone#(res): 920-716-0643 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: JTRENT1@GMAIL.COM Tag#:
Purchased Date: 17 JAN 25 :
Delivery Date: 01 MAY 25 :
InService Date: :
Serial#: 4X4FFLN22S1908672 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - Missing the cover on W 1021 FORES
awning arm rear most awning the back arm
CAUSE: Missing awning arm cover
CORRECTION: Obtained a cover from parts it's off of
a extra awning arm so no part number
attached REQUESTING .3 APPROVED .3
WARR COMPLAINT: WARRANTY REPAIR 2 - The curtain bracket W 1021 FORES
in the bedroom ds bis not attached to
the wall
CAUSE: Improper install
CORRECTION: Installed 2 screws to curtain bracket
and installed curtain REQUESTING .1
APPROVED .1
WARR COMPLAINT: WARRANTY REPAIR 3 - The black and grey 1 W 1021 FORES
are switched while filling the toilet it
reads on grey one
CAUSE: Mfg hooked up the black and grey 1 wires
backwards so grey reads black black
reads grey 1
CORRECTION: Removed the panels to access wires moved
the black wire and grey wire around
tested now monitor is reading correctly
reinstalled the panels then filled all
tanks to full to ensure they were
reading accurately and they are
REQUESTING .5 APPROVED .5
WARR COMPLAINT: WARRANTY REPAIR 4 - cover for awning arm W 1021 FORES
is missing

Continued on page 2

Work Order : 11878B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CAUSE:   Missing Please order new black cover for
         rear awning arms top cover the one from
         parts did not fit
CORRECTION: REQUESTING .3 SAME AS LINE 1

```

```

*****
Job # Part No Description           PARTS           Bill to Qty Price Total
*****
WARR0 82203031 AWNING PART 3M-1: FRONT DRIV W-1021 1 7.20 7.20

```

```

*****
Job# Lab Code Description           LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.25 140.00 35.00
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.05 140.00 7.00
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.05 140.00 7.00
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.27 140.00 37.80
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.13 140.00 18.20
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.03 140.00 4.20
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.07 140.00 9.80
ARR04 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.50 140.00 70.00
ARR01 WARR MANUFACTURER WARRANTY TD W-1021 0.30 140.00 42.00

```

```

*****
Job # Excode Description           EXTRAS bill to Qty Price Total
*****
ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1021 1.00 0.00 0.00
ARR04 FRT FREIGHT AWNING FRT HEAD CO W-1021 1.00 18.41 18.41

```

```

*****
BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
W 1021 7.20 231.00 0.00 18.41 0.00 256.61
Totals 7.20 231.00 0.00 18.41 0.00 256.61

```

&k2S
&k0S