



8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494

[ spreading the joy of the camping lifestyle ]

(715) 325-5170  
mail@greenewayrv.com  
www.greenewayrv.com

W/O: 11894B  
Promised Date:  
25 DEC 25



WO #: 11894B

Customer Name: 17677 - KADRMAS,  
HARVEY

Address: 9301 SYCAMORE LANE  
BISMARCK, ND

Postal/Zip: 58504

Phone#(res): 701-391-0346

Phone#(bus):

Cell Phone:

Email: HKADRMAS@BEKTEL.COM

Date In: 03 MAY 25  
Promised Date: 25 DEC 25

Purchased Date: 15 APR 25

Delivery Date: 02 MAY 25

InService Date:

Serial#: 573TE201XR7702021

Author: KOTT

Stock No: 11013

Year: 2024

Manufacturer: GRAND DESIGN

Brand: IMAGINE AIM

Model: 16BL

Miles/Hrs: 0

Exterior Color:

Unit Type: TT-TRAVEL TRAILER

License#:

Tag#: DB: 5/3

**Job #WARR01 - Warranty**

COMPLAINT: WARRANTY REPAIR 1 - The trim is loose beneath the bunk area

CAUSE: Loose

CORRECTION: Used pin nailer to secure the trim

REQUEST .10 HOURS LABOR

WARRANTY AUTH .20 HOURS OF LABOR

**Labor**

Job #	Description	Total
WARR01	MISC LABOUR CODE (WARRANTY)	N/C

**Other Services**

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES - EXTERNAL	1.00	N/C	N/C

**Subtotal for Job #WARR01: 0.00**

**Job #WARR02 - Warranty**

COMPLAINT: WARRANTY REPAIR 2 - Putty marks on paneling and sofa in unit

CAUSE: Excess putty and nail holes needed folling

CORRECTION: Used putty to fill holes then wiped away excess putty

REQUEST .30 HOURS LABOR

WARRANTY AUTH .20 HOURS OF LABOR

**Labor**

Job #	Description	Total
WARR02	MISC LABOUR CODE (WARRANTY)	N/C

**Subtotal for Job #WARR02: 0.00**

**Job #WARR03 - Warranty**

COMPLAINT: WARRANTY REPAIR 3 - 15 amp fuse missing in converter

CAUSE: Missing fuse

CORRECTION: Put new 15 amp fuse in

REQUEST .10 LABOR

WARRANTY AUTH .20 HOURS OF LABOR

Customer #: 17677  
KADRMAS, HARVEY



W/O: 11894B  
Promised Date: 25 DEC 25

<b>Labor</b>		Total
Job #	Description	
WARR03	MISC LABOUR CODE (WARRANTY)	N/C
<b>Subtotal for Job #WARR03:</b>		<b>0.00</b>

**Job #WARR04 - Warranty**

COMPLAINT: WARRANTY REPAIR 4 - THE LOCK ON THE COMPARTMENT DOOR DOES NOT UNLCOK OR LOCK- IT JUST SPINS

CAUSE: FAULTY LOCK

CORRECTION: R&R LOCK  
REQUEST .30 HOURS LABOR  
WARRANTY AUTH .20 HOURS OF LABOR

<b>Labor</b>		Total
Job #	Description	
WARR04	MANUFACTURER WARRANTY REPAIR	N/C

<b>Parts</b>				
Part #	Description	Qty	Price	Total
822090502	90* ENTRY DOOR CATCH BLACK	1.00	N/C	N/C
756815001250	7/8" THUMB COMPARTMENT LO	1.00	N/C	N/C

**Subtotal for Job #WARR04: 0.00**

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00  
**WORK ORDER TOTAL: 0.00**

**CUSTOMERS CLEAR RECEIPT**

The above described property has been received, and after having examined the work done, the material furnished, both the work and material has been found to be satisfactory.  
I agree that any goodwill repairs are in no way an admission that the vehicle suffers from any defect or issue, or that the repair should be covered under warranty.

Customer Signature : \_\_\_\_\_

Date: 06 May 2025



Customer #: 17677  
KADRMAS, HARVEY

