

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11907

Date In:	19 APR 25	Author:	MGRAY
Promised Date:	31 JUL 25	Stock No:	11028
:	:	Year:	2024
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	REFLECTION 150 SERIES
:	MIDDLEBURY, IN	Model:	270BN
Postal/Zip:	46540	Miles/Hrs:	0
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	14 MAR 24	:	:
Delivery Date:	15 APR 24	:	:
InService Date:	:	:	:
Serial#:	573FR3126R3348424	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  ADDED 4/14 AT PICK UP OF UNIT. WARRANTY W    1020    GRAND
          REPAIR 1 - MATT LOOKED AT WITH CUST,
          BELIVES IT MAY HAVE A BAD ABS BOARD.
          NEED FURTHER DIRECTION.
          CAUSE:      Diagnos abs brake system. Not getting
                      any power to brakes or turn signals.
                      Tried testing power to brakes, but it
                      set off an alarm on control board. The
                      system is made by precision circuits.
                      Pics uploaded. Need new control board.
                      Scott McDaniel with SRT team looked at
                      unit and confirmed needing a replacement
                      control board.
          CORRECTION: Replaced control board, brake lights and
                      turn signals still inop.
WARR    COMPLAINT:  7 way Distribution Control Board did not W    1020    GRAND
          solve previous complaint about brake and
          turn lights not working.
          CAUSE:      Discussed further with Scott McDaniel
                      from SRT team and he recommended
                      checking the harness at the ABS module
                      in the underbelly.
          CORRECTION: Lowered underbelly and found one of the
                      weatherpac connectors to the ABS module
                      unplugged with a broken clip. Plugged in
                      and secured with nylon cable ties.
                      Brake and turn lights check OK. *THIS
                      IS A TEMPOARY REPAIR SO THE CUSTOMER CAN
```

Continued on page 2

Work Order : 11907

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                USE THEIR UNIT WHILE A REPLACEMENT
                                HARNESS IS ORDERED* Will need to replace
                                ABS harness in the near future.
WARR    COMPLAINT:  Replace ABS Harness                        W      1020    GRAND
        CAUSE:      Harness defective for ABS sensor board
                                connection.
        CORRECTION:  Factory sent replacement harness.
                                Removed original harness installed new
                                harness exactly where previous was.
                                Wired new harness by swapping in new
                                harness one wire at a time. Works great.

```

```

*****
Job # Part No   Description                PARTS                Bill to   Qty    Price    Total
*****
WARR0 822030153 CONTROL BOX 7 WAY BATTERY 5 W-1020        1    217.40   217.40
WARR0 82200310  ABS MAIN WIRE HARNESS 50'   W-1020        1    184.83   184.83

```

```

*****
Job#  Lab Code  Description                LABOUR    Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR      W-1020    0.00   140.00    0.00
ARR01 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.50   140.00    70.00
ARR01 Z992      MISC LABOUR CODE (WARR MF  W-1020    0.60   140.00    84.00
ARR02 Z992      MISC LABOUR CODE (WARR MF  W-1020    1.50   140.00   210.00
ARR03 Z992      MISC LABOUR CODE (WARR RW  W-1020    1.01   140.00   141.40
ARR03 Z992      MISC LABOUR CODE (WARR RW  W-1020    0.21   140.00    29.40
ARR03 Z992      MISC LABOUR CODE (WARR RW  W-1020    1.78   140.00   249.20

```

```

*****
Job #  Excode   Description                EXTRAS                bill to   Qty    Price    Total
*****
ARR01  FRT      FREIGHT                        W-1020    1.00    39.24    39.24
ARR03  FRT      FREIGHT FOR JOB WARR03        W-1020    1.00    35.49    35.49

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1020        402.23    784.00    0.00     74.73    0.00    1,260.96

        Totals    402.23    784.00    0.00     74.73    0.00    1,260.96

```

&k2S
&k0S