



Warranty Claim Form

Date: 8/20/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3126R3348424
Reflection 270BN
Retail Purchase Date: 4/15/2024
Work Started: 7/11/2025
Work Completed: 7/11/2025

Claim Status: Paid
Dealer Work Order #: 11907
Unit Offline Date: 10/25/2023

Claim #: 919732
Labor: \$280.00
Parts: \$184.34
Shipping: \$14.16
Total: \$499.83

Notes: ***HOLD*** reached out to pre auth mls 8/18

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Bradley Leverance
1681 Bittersweet Dr
Rudolph, Wisconsin 54475
United States
715-570-6232

Operation Line # 1

Flat Rate Code: 120023 Brakes - R & R ABS Harness

Fault Code: Damaged/Maintenance

Problem: Replace harness

Hours: 2

Cause: The retaining clip on the harness broke and the plug fell out of the abs module. It wouldn't stay plugged in, so we ziptied the plug in temporarily while the new harness was on order.

A m o u n t :
280.00

Remedy: Without the module plugged in, the customer lost left turn, right turn, brakes and brake lights. We worked with SRT and they confirmed we needed to order and replace the harness AFTER he had us \$0.00 replace the front 7 way distribution board (has the batter disconnect built into it) which did not fix the issue.

Sublet Repairs:
\$0.00

Manufacturer #: 1

Model #: 1

Serial #: 1

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
120310 ABS MAIN WIRE HARNESS 50'	ABS MAIN WIRE HARNESS 50'		1	1	184.34

Operation Line # 2

Flat Rate Code: 950003 Misc. Charges - Handling Fee

Fault Code: No Problem Identified

Problem: Invoice 1421193

Hours: 0

Cause: Invoice 1421193

Amount: 0.00

Remedy: Invoice 1421193

Sublet Repairs: \$21.33

Manufacturer #:

Model #:

Serial #: