



Warranty Claim Form

Date: 6/27/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR2820S3353351
Reflection 22RK
Retail Purchase Date: 5/30/2025
Work Started: 6/6/2025
Work Completed: 6/6/2025

Claim Status: Paid

Dealer Work Order #: 11923B

Unit Offline Date: 4/16/2025

Claim #: 903410

Labor: \$84.00

Parts: \$162.92

Shipping: \$14.16

Total: \$261.08

Notes: *SECOND REQUEST* Job 2- Please attach photos of ALL the vendor markings around the collar of the defective bottle. 6/16 DW cc-5/27/25 Please hold parts for 30 days after claim is filed

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

GREGORY BRONIEC
1142 W QUEENS WAY
NEKOOSA, Wisconsin 54457
United States
7154591101

Operation Line # 1

Flat Rate Code: 160039 Electric Leveling - Electric Leveling - *Fault Code:* Improper Installation/Build
Calibrate Control Pad

Problem: Leveling System

Hours: .2

Cause: Zero point net set incorrectly.

Amount: 28.00

Remedy: Manually leveled coach using level, set zero point, retracted all and tested. Working
as expected now.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 240001 Bottles - R & R LP Bottle

Fault Code: Component Failure

Problem: LP Tank won't take a fill.

Hours: .2

Cause: LP tank would not fill, tried it 3 times, must have defective valve.

Amount: 28.00

Remedy: Replaced 30LB LP tank with a new tank from retail shelf.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	0.00
240011 BOTTLE LP 30# TANK WHITE DOT/TC APPROVED	BOTTLE LP 30# TANK WHITE DOT/TC APPROVED		1	1	110.14

Operation Line # 3

Flat Rate Code: 510008 Decals - R&R Sidewall Decal/Logo/Die *Fault Code:* Damaged/Maintenance Cut

Problem: Manufacturer VIN sticker

Hours: .2

Cause: VIN sticker printed defective, has a line through it.

Amount: 28.00

Remedy: Needs to be remade, parts of it are illegible. R&R sticker

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>						<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
510315 LABEL VIN TAG REPLACEMENT USA	LABEL	VIN	TAG	LABEL	VIN	TAG		1	1	52.78