



Warranty Claim Form

Date: 1/26/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE3621S6654992
Imagine 3100RD
Retail Purchase Date: 6/12/2025
Work Started: 6/7/2025
Work Completed: 1/13/2026

Claim Status: Paid
Dealer Work Order #: 11925B
Unit Offline Date: 4/30/2025

Claim #: 959403
Labor: \$868.00
Parts: \$64.55
Shipping: \$31.50
Total: \$971.50

Notes: *adjusted shipping / handling fee to the items approved on invoices mls 1/15 *LINE 1 parts added dont reflect job stated needed mls 1/14 cc-10/16/25 dealer requesting additonal time on line 1-420013 cc-6/18/25 Please hold parts for 30 days after claim is filed

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

BRIAN ZOHIMSKY
15 HEMLOCK ST
RHINELANDER, Wisconsin 54501
United States
7155500448

Operation Line # 1

Flat Rate Code: 420013 Lights (Interior) - R&R LED Light *Fault Code:* Component Failure

Problem: Light above driver side love seat does not light up. Found a 15 amp fuse blown, replaced it then switched light on and the new fuse blew. *Hours:* 6

Cause: Short in the light. Wired a different light up there and it is not blowing a fuse and lights up. Put a *A m o u n t :* resettable fuse in the fuse box and checked the voltage at the wires for the light and it's at 13.4 volts. 840.00
Checked the wiring under the slide to make sure there wasn't any damage and from what I can see the wiring is fine. Hooked up a different light fixture and left it on for over two hours and it never popped a fuse. Need to replace the light.

Remedy: We will need to remove the panel on that wall, remove the distribution panel to access the wire for *S u b l e t* replacement. Then open up the under belly to run a new wire from the panel to the USB charge port to *R e p a i r s :* eliminate the existing wire that has a dead short causing the fuse to blow. Will need 18' of 12-gauge wire. \$0.00

Manufacturer #: Dream Lighting

Model #: x

Serial #: x

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
421487 LIGHT INTERIOR 21" 5000K COOL WHITE STRIP LIGHT W/WHITE SLEEVE W/ 3M TAPE	LIGHT INTERIOR 21" 5000K COOL WHITE STRIP LIGHT W/WHITE SLEEVE W/ 3M TAPE		1	1	0.00
673708 COUNTERTOP 5/8 X 12 X 24 KUNA BLACK NG 3D ROUND OVER LIGHT BOARD HARDWOOD 4C-171-F	COUNTERTOP 5/8 X 12 X 24 KUNA BLACK NG 3D ROUND OVER LIGHT BOARD HARDWOOD 4C-171-F		1	1	64.55

Operation Line # 2

Flat Rate Code: 610009 Moldings/Trims - R&R Decorative Wood *Fault Code:* Improper Installation/Build Trim (per piece)

Problem: Routed out decorative slots below fireplace, the finish is jagged and peeling.

Hours: .2

Cause: Rough cut from manufacturing.

Amount: 28.00

Remedy: Used sandpaper and lightly sanded the edges.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 3

Flat Rate Code: 950003 Misc Charges - Packaging/Handling *Fault Code:* No Problem Identified Fee

Problem: Invoice 1454314 - \$7.45 Invoice 1444988 - \$2.70

Hours: 0

Cause: Invoice 1454314 - \$7.45 Invoice 1444988 - \$2.70

Amount: 0.00

Remedy: Invoice 1454314 - \$7.45 Invoice 1444988 - \$2.70

Sublet Repairs: \$7.45

Manufacturer #:

Model #:

Serial #: