

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 11937

|                 |                        |                 |                   |
|-----------------|------------------------|-----------------|-------------------|
| Date In:        | 25 APR 25              | Author:         | MZYWICKI          |
| Promised Date:  | 25 DEC 25              | Stock No:       | 11041             |
| :               | :                      | Year:           | 2024              |
| Customer Name:  | 17579 - FORSLUND, LORI | Manufacturer:   | GRAND DESIGN      |
| Address:        | 3833 REDSTONE DR       | Brand:          | REFLECTION TT     |
| :               | JANESVILLE, WI         | Model:          | 315RLTS           |
| Postal/Zip:     | 53548                  | Miles/Hrs:      | :                 |
| Phone#(res):    | 6082896302             | Exterior Color: | :                 |
| Phone#(bus):    | :                      | Unit Type:      | TT-TRAVEL TRAILER |
| Cell Phone:     | :                      | License#:       | :                 |
| Email:          | NONE@GMAIL.COM         | Tag#:           | :                 |
| Purchased Date: | 07 DEC 24              | :               | :                 |
| Delivery Date:  | 08 MAR 25              | :               | :                 |
| InService Date: | :                      | :               | :                 |
| Serial#:        | 573TR3824R9925585      | :               | :                 |

\*\*\*\*\*

| Job # | Description | JOB INFORMATION                                                                                                                                                                                                                                                                            | Type | Bill To     |
|-------|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-------------|
| 1     | COMPLAINT:  | CUSTOMER REQUEST SERVICE CALL TO THEIR UNIT RUSTIC RIDGE CASTLE ROCK SITE# 32                                                                                                                                                                                                              | E    | 17579 FORSL |
|       | CORRECTION: | SERVICE CALL COMPLETE-                                                                                                                                                                                                                                                                     |      |             |
| 2     | COMPLAINT:  | CUSTOMER STATES THERE IS WATER IN THEIR UNIT BETWEEN THE ENTRY DOOR AND THE DINETTE. ABOUT AN 18" SQUARE. CMR STATES THAT NONE OF THE SLIDES WERE OUT WHEN THEY CHECK ON UNIT. CMR ALSO STATES THEY CANNOT SEE ANY VISIABLE WATER DAMAGE TO CEILING OR WALLS OF UNIT. WOULD LIKE DIAGNOSED | W    | 1020 GRAND  |
|       | CAUSE:      | slide adjustments need on door side<br>slide the top of slide was not touching on right side of slide NEED .70 FOR ENTIRE REPAIR.                                                                                                                                                          |      |             |
|       | CORRECTION: | adjustments made to to on door side<br>slide is now closing correctly                                                                                                                                                                                                                      |      |             |
| 3     | COMPLAINT:  | CMR STATES THAT THEY ARE HAVING SOME ELECTRICAL ISSUES. CMR STATES THERE IS SOMETHING GOING ON WITH THE FURNACE WHERE IT WILL KICK ON BUT THEN OTHER ELECTRICAL THINGS SHUT OFF. CMR ALSO STATED THAT THE OVERHEAD LIGHTS TURNED ON BY ITSELF ALONG WITH THE RADIO TURNING ON BY ITSLEF    | W    | 1020 GRAND  |
|       | CAUSE:      | pics taken what I found was when ever you turn the furnace on the sensor light would come on in pantry NEED 1.20 FOR                                                                                                                                                                       |      |             |

Continued on page 2

Work Order : 11937

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
REPAIR.
CORRECTION: so I removed the black air intake cover
              to gain excess to negative block tight
              all screws that hold wires and tested
              furnace multiple time after and the
              light now stays off customer will keep
              eye on it

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
  2  Z992      MISC LABOUR CODE (WARR JS  W-1020  0.50  140.00  70.00
  3  Z992      MISC LABOUR CODE (WARR JS  W-1020  0.50  140.00  70.00

```

```

*****
Job #  Excode   Description  EXTRAS  bill to  Qty  Price  Total
*****
  1  SSE       SHOP SUPPLIES - EXTERNAL  E-17579  1.00  0.00  0.00
  1  SC        SERVICE CALL             E-17579  17.00  3.75  63.75

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
E   17579      0.00   0.00   0.00   63.75  3.51  67.26
W   1020      0.00  140.00   0.00   0.00   0.00  140.00

Totals      0.00  140.00   0.00  63.75  3.51  207.26

```

&k2S  
&k0S