

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11942B

Date In: 16 MAY 25 Author: KOTT
Promised Date: 23 MAY 25 Stock No: 11317
: Year: 2025
Customer Name: 15413 - SLAASTED, RALP Manufacturer: FOREST RIVER
Address: 180 MILL AVE Brand: PUMA DESTINATION
: UNION GROVE, WI Model: 403LFT
Postal/Zip: 53182 Miles/Hrs: 0
Phone#(res): 2623215404 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: SLAASTED@SBCGLOBAL.NET Tag#:
Purchased Date: 26 APR 25 :
Delivery Date: 23 MAY 25 :
InService Date: :
Serial#: 4X4TPUS22SP105237 :

```
*****
Job # Description JOB INFORMATION Type Bill To
*****
WARR COMPLAINT: WARRANTY REPAIR 1 - The upper windows W 1021 FORES
      have silicone smeared on the interior
      and exterior of the window glass
CAUSE: Sticky smeary stuff on upper windows
      NEED .30 FOR REPAIRS.
CORRECTION: Removed what I could on inside of
      windows
WARR COMPLAINT: WARRANTY REPAIR 2 - Floor in front of ds W 1021 FORES
      loveseat has a very sharp piece of metal
      protruding from it
CAUSE: Mfg left something sharp sticking out of
      floor
CORRECTION: I hammered down the sharp metal then
      sealed the are
WARR COMPLAINT: WARRANTY REPAIR 3 -lino has sticky stuff W 1021 FORES
      all over it everywhere
CAUSE: Silicone on lino from mfh NEED .30 FOR
      REPAIRS
CORRECTION: Used quick solve to clean the areas also
      vacuumed up slot of metal shavings to
      prevent them from cutting lino
WARR COMPLAINT: WARRANTY REPAIR 4 - bottom step going to W 1021 FORES
      loft has staple protruding from it
CAUSE: Protruding staple from mfh NEED .10 FOR
      REPAIR
CORRECTION: Hard to get pic but it could rip a he
      ole in someone's foot hammered down into
      floor base
```

Continued on page 2

Work Order : 11942B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 5 - carpeting on stairs  W    1021  FORES
        going to loft is filthy and stained
        CAUSE:      Stains on carpet from mfh. NEED .30 FOR
                   REPAIRS
        CORRECTION: Used spray cleaner to remove the stains
                   on all of the steps carpeting
WARR    COMPLAINT:  WARRANTY REPAIR 6 -the bed will not stay W    1021  FORES
        up with struts that were installed by
        factory
        CAUSE:      The struts are not strong enough to hold
                   bed up they look to be 100# Please order
                   2 new bed struts 20-21" long and over
                   100 # I've attached pic of numbers on
                   the struts. NEED .50 FOR REPAIRS.
        CORRECTION: .....
2       Transferred to GRV*11942C on 22 MAY 25 Estimate    W    1021  FORES
        amount was 0.00 STEP RECALL 25V245,2025-203 MORRYDE
        DETACHABLE STEPS. INSPECT AND CORRECT IF NEEDED.
    
```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1021  0.50  140.00  70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1021  0.50  140.00  70.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1021  0.50  140.00  70.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1021  0.50  140.00  70.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1021  0.50  140.00  70.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD  W-1021  0.50  140.00  70.00
     2 WARR      MANUFACTURER WARRANTY      W-1021  0.00  140.00   0.00
    
```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021  1.00  0.00  0.00
    
```

```

*****
                                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W    1021      0.00  420.00  0.00  0.00  0.00  420.00
     Totals    0.00  420.00  0.00  0.00  0.00  420.00
    
```

&k2S
&k0S