

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 11942B

Date In: 16 MAY 25 Author: KOTT
 Promised Date: 25 DEC 25 Stock No: 11317
 : Year: 2025
 Customer Name: 15413 - SLAASTED, RALP Manufacturer: FOREST RIVER
 Address: 180 MILL AVE Brand: PUMA DESTINATION
 : UNION GROVE, WI Model: 403LFT
 Postal/Zip: 53182 Miles/Hrs: 0
 Phone#(res): 262-321-5404 Exterior Color:
 Phone#(bus): Unit Type: TT-TRAVEL TRAILER
 Cell Phone: License#:
 Email: SLAASTED@SBCGLOBAL.NET Tag#:
 Purchased Date: 26 APR 25 :
 Delivery Date: 23 MAY 25 :
 InService Date: :
 Serial#: 4X4TPUS22SP105237 :

```
*****
Job # Description JOB INFORMATION Type Bill To
*****
WARR COMPLAINT: WARRANTY REPAIR 1 - The upper windows W 1021 FORES
      have silicone smeared on the interior
      and exterior of the window glass
CAUSE: Sticky smeary stuff on upper windows
      NEED .30 FOR REPAIRS.
CORRECTION: Removed what I could on inside of
      windows WARRANTY AUTH: .30 HOURS
WARR COMPLAINT: WARRANTY REPAIR 2 - Floor in front of ds W 1021 FORES
      loveseat has a very sharp piece of metal
      protruding from it
CAUSE: Mfg left something sharp sticking out of
      floor
CORRECTION: I hammered down the sharp metal then
      sealed the are WARRANTY AUTH: .50 HOURS
WARR COMPLAINT: WARRANTY REPAIR 3 -lino has sticky stuff W 1021 FORES
      all over it everywhere
CAUSE: Silicone on lino from mfh NEED .30 FOR
      REPAIRS
CORRECTION: Used quick solve to clean the areas also
      vacuumed up slot of metal shavings to
      prevent them from cutting lino WARRANTY
      AUTH: .30 HOURS
WARR COMPLAINT: WARRANTY REPAIR 4 - bottom step going to W 1021 FORES
      loft has staple protruding from it
CAUSE: Protruding staple from mfh NEED .10 FOR
      REPAIR
CORRECTION: Hard to get pic but it could rip a he
      ole in someone's foot hammered down into
*****
```

Continued on page 2

Work Order : 11942B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:           floor base WARRANTY AUTH: .10 HOURS
        WARRANTY REPAIR 5 - carpeting on stairs W   1021   FORES
        going to loft is filthy and stained
        CAUSE:              Stains on carpet from mfh. NEED .30 FOR
        REPAIRS
        CORRECTION:        Used spray cleaner to remove the stains
        on all of the steps carpeting WARRANTY
        AUTH: .30 HOURS
WARR    COMPLAINT:           WARRANTY REPAIR 6 -the bed will not stay W   1021   FORES
        up with struts that were installed by
        factory
        CAUSE:              The struts are not strong enough to hold
        bed up they look to be 100# Please order
        2 new bed struts 20-21" long and over
        100 # I've attached pic of numbers on
        the struts. NEED .50 FOR REPAIRS.
        CORRECTION:        ..... WARRANTY DENIED: THE STRUTS
        THAT ARE ON HERE ARE THE CORRECT STRUTS
        FOR THIS BED- WARRANTY DOES NOT COVER
        UPGRADES OR MODIFICATIONS-
2       Transferred to GRV*11942C on 22 MAY 25 Estimate W   1021   FORES
        amount was 0.00 STEP RECALL 25V245,2025-203 MORRYDE
        DETACHABLE STEPS. INSPECT AND CORRECT IF NEEDED.

```

```

*****
Job # Part No  Description      PARTS      Bill to  Qty  Price  Total
*****
WARR0 822072660 STRUT, BED, GAS LIFT, 20", W-1021    0    4.91    0.00

```

```

*****
Job# Lab Code  Description      LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.30 140.00 42.00
ARR02 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.50 140.00 70.00
ARR03 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.30 140.00 42.00
ARR04 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.10 140.00 14.00
ARR05 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.30 140.00 42.00
ARR06 Z992     MISC LABOUR CODE (WARR HOD W-1021    0.10 140.00 14.00
2 WARR     MANUFACTURER WARRANTY W-1021    0.00 140.00 0.00

```

```

*****
Job # Excode  Description      EXTRAS      bill to  Qty  Price  Total
*****
ARR01 SSE     SHOP SUPPLIES - EXTERNAL W-1021    1.00 0.00    0.00

```

Continued on page 3

Work Order : 11942B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	0.00	224.00	0.00	0.00	0.00	224.00
	Totals	0.00	224.00	0.00	0.00	0.00	224.00

&k2S
&k0S