

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11942C

Date In:	22 MAY 25	Author:	DLUCAS
Promised Date:	31 MAY 26	Stock No:	11317
:	:	Year:	2025
Customer Name:	15413 - SLAASTED, RALP	Manufacturer:	FOREST RIVER
Address:	180 MILL AVE	Brand:	PUMA DESTINATION
:	UNION GROVE, WI	Model:	403LFT
Postal/Zip:	53182	Miles/Hrs:	0
Phone#(res):	262-321-5404	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	SLAASTED@SBCGLOBAL.NET	Tag#:	DB: 3/10
Purchased Date:	26 APR 25	:	:
Delivery Date:	23 MAY 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS22SP105237	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
2       COMPLAINT:  STEP RECALL 25V245,2025-203 MORRYDE      W      1021    FORES
        DETACHABLE STEPS. INSPECT AND CORRECT IF
        NEEDED.
        CAUSE:      Recall
        CORRECTION: Replace with new one
1       COMPLAINT:  CUSTOMER STATES THAT THEY WERE NOTICING W      1021    FORES
        WATER DROPPIGN ABOVE THE WHEELS WHEN HE
        HAD THE TANKS PRESSURIZED- HE ALSO
        NOTICE WATER DRIPPING UNDER THE WATER
        HEATER- NEEDS TO BE DIAGNOSED-
        CAUSE:      The o ring was not properly seated
        properly which caused the hot water line
        in the back of the hot water tank to
        leak
        CORRECTION: Put in a new o ring turn the water back
        on, and I have no leaks  REQ: .50
3       COMPLAINT:  ADDED 11/3- CUSTOMER STATES THAT THE      W      1021    FORES
        FURNACE IS NOT OPERATING- SPECIFICALLY
        IN THE BEDROOM- CUSTOMER STATES THAT THE
        FURNACE WILL TURN ON BUT WILL NOT BLOW
        WARM AIR
        CAUSE:      Furnace will not operate in bedroom. The
        thermostat in the bedroom is for the a/c
        only not the furnace. The thermostat in
        the hall is for the furnace has to be
        set to zone 1 and then the furnace works
        in bedroom
        CORRECTION: Furnace will not operate in bedroom. The
```

Continued on page 2

Work Order : 11942C

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                thermostat in the bedroom is for the a/c
                                only not the furnace. The thermostat in
                                the hall is for the furnace has to be
                                set to zone 1 and then the furnace works
                                in bedroom   REQ: .10
4      COMPLAINT:  CMR STATES THAT THE BEDROOM WINDOW DOES  W    1021    FORES
                                NOT CLOSE ALL THE WAY- IN THE LOWER LEFT
                                CORNER THERE IS A GAP WHEN YOU CLOSE THE
                                WINDOW
      CAUSE:      1000 DEFECT FROM MANUFACTURER Window
                                does not seal in the left corner   Ti
                                will need a new window
      CORRECTION: R&R WINDOW REQ: 2.50
WMH    COMPLAINT:  WINTERIZE WATER SYSTEM & TRAPS -SELF    I    PDI    PRE-D
                                CONTAINED - MOTORIZED
      CAUSE:      Had to on winterize to do my diag
      CORRECTION: Rewinterize

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
2      82204078      RECALL KIT MORRYDE STEPS W-1021      1      0.00      0.00
1      742979164351  SINGLE 1/2" SWIVEL SEAL W-1021      1      1.91      1.91
WMH    009114950003  -50 F GLYCERIN FREE BASE I-PDI      3      4.80      14.40

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to      Hrs      Rate      Total
*****
2  WARR      MANUFACTURER WARRANTY  JL  W-1021      0.39      140.00      54.60
2  WARR      MANUFACTURER WARRANTY  JL  W-1021      0.11      140.00      15.40
1  WARR      MANUFACTURER WARRANTY  JL  W-1021      0.00      140.00      0.00
1  WARR      MANUFACTURER WARRANTY  JL  W-1021      0.09      140.00      12.60
1  WARR      MANUFACTURER WARRANTY  JL  W-1021      0.21      140.00      29.40
1  WARR      MANUFACTURER WARRANTY  JL  W-1021      0.20      140.00      28.00
3  WARR      MANUFACTURER WARRANTY  JL  W-1021      0.50      140.00      70.00
4  WARR      MANUFACTURER WARRANTY  JL  W-1021      0.00      140.00      0.00
4  WARR      MANUFACTURER WARRANTY  JL  W-1021      0.14      140.00      19.60
WMH W495      WINTERIZE RV (WATER SY JL  I-PDI      1.40      70.00      98.00
WMH W495      WINTERIZE RV (WATER SY JL  I-PDI      0.00      70.00      0.00

```

```

*****
Job #  Excode      Description  EXTRAS      bill to      Qty      Price      Total
*****
WMH  SSE      SHOP SUPPLIES - EXTERNAL  I-PDI      1.00      0.00      0.00

```

Continued on page 3

Work Order : 11942C

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	PDI	14.40	98.00	0.00	0.00	0.00	112.40
W	1021	1.91	229.60	0.00	0.00	0.00	231.51
	Totals	16.31	327.60	0.00	0.00	0.00	343.91

&k2S
&k0S