

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2299928
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	4X4TCRS28SS234850
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$140.00	SITE/WAREHOUSE	020 / 020
OWNER INFORMATION		ITEM #	CRT40CRS
		DEALER RO #	11983B
		CLAIM START DATE	05/15/2025
		CLAIM END DATE	05/20/2025

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-103-24-00-001119	Carpet - Interior/Flooring/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2025-05-15 11:02:00 :: Complaint: The floor coverings on slides have stains on them. Cause: Marks on floor covering from manufacturing process. Correction: Cleaned floor coverings.			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$28.00
	Serial#	Appr Hrs	0.20	Appr Labor Amt \$28.00
	Notes			
	AUTHORIZED			

Labor

Line# 2	Operation Code	Operational Description		
	30-91-24-00-000923	Furniture - Sofa or Chairs - Interior/Living Quarters, Sofa, Chair/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2025-05-15 11:03:21 :: Complaint: Sofa has marks on it. Cause: Marks from factory Correction: Cleaned sofa with soap and cloth to remove marks.			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$28.00
	Serial#	Appr Hrs	0.20	Appr Labor Amt \$28.00
	Notes			
	AUTHORIZED			

Labor

Line# 3

Operation Code

20-89-01-00-000880

Operational Description

MaxxAir Fan Blade - Exterior/Power Roof Vent (MaxxAir)/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-05-15 11:04:38 :: Complaint: Screen hitting fan in bathroom and makes a lot of noise. Cause: Misaligned. Correction: Went to the roof and adjusted the blades as much as possible, did this 3 times it seems to not be hitting anymore. Tested on all four speeds.

Model# NA

Dlr Sub Hrs0.20

Sub Labor Amt \$28.00

Serial# NA

Appr Hrs0.20

Appr Labor Amt \$28.00

Notes

DID YOU HAVE PHOTOS OF THIS?

Labor code does not require photos. Thank you.

I APOLOGIZE I THOUGHT I UPDATED THE REPAIR CODE. THE REPAIR CODE YOU USED IS FOR A RANGE. THE DESCRIPTION SAYS RANGE HOOD. THIS IS THE INCORRECT CODE. I HAVE UPDATED THE CODE AND PHOTOS ARE REQUIRED.

Photo uploaded.

Labor
Line# 4

Operation Code
70-178-01-00-002141

Operational Description
Range-Stove Top Burner - Appliances/Range (Suburban)/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : greeneway@dealer-advisors.com, 2025-05-15 11:05:42 :: Complaint: Stove is making a really annoying rattling noise. Cause: Unsure on cause. Correction: Noting only.

Model# 1

Dlr Sub Hrs 0.00

Sub Labor Amt \$0.00

Serial# 1

Appr Hrs 0.00

Appr Labor Amt \$0.00

Notes
NO REPAIR TO BE MADE

NOTED

Submitted	Labor Amt	\$84.00	Approved	Labor Amt	\$84.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$84.00		Total	\$84.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.