

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 2572408
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TCRS23SS234660
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 020 / 020
 ITEM # CRT40CDL
 DEALER RO # 12011B
 CLAIM START DATE 02/05/2026
 CLAIM END DATE 02/11/2026

Labor rate: \$140.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 Operation Code Operational Description
 30-103-04-00-001119 Carpet - Interior/Flooring/Clean/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2026-02-05 16:57:13 :: Complaint: The floor coverings have some stains on them. Cause: Stained from manufacturer. Correction: Used quick solve to remove the spots on the floor covering.

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$70.00
Serial#	Appr Hrs	0.50	Appr Labor Amt \$70.00

Notes
 AUTHORIZED

Labor

Line# 2 Operation Code Operational Description
 20-44-19-00-000553 Roof Moldings - Front or Rear - Exterior/Roof/Reseal/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2026-02-05 16:58:17 :: Complaint: The roof needs dicor at rear ODS corner and in the vent tabs of 3 vents. Cause: Sealant needed, missed from manufacturer. Correction: Cleaned the areas and then sealed around the areas needing it.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$28.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$28.00

Notes

Part

Line# 1 Item # Description
 USERPART DCR501LSW-1 Dicor self leveling lap sealant - white
 Model # Serial # Part tag

Sub Qty	1.00	Sub Dlr Price	\$8.72	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$8.72	Appr Freight	\$0.00

Notes

Labor

Line# 3 Operation Code Operational Description
 30-102-12-00-001096 Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2026-02-05 16:59:23 :: Complaint: To the left of the patio, the trim is coming off at the bottom. Cause: Loose trim. Correction: Used a pin nailer to resecure the trim into place.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$28.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$28.00

Labor
Line# 4

Notes
AUTHORIZED

Operation Code
30-103-24-00-001125

Operational Description
Linoleum - Interior/Flooring/Repair/No Tread Code

Complaint, Cause, Correction
Original Note : greeneway@dealer-advisors.com, 2026-02-05 17:00:20 :: Complaint: The flooring in the kitchen has a few deep scratches near the island. Cause: Scratches in the lino from the manufacturer. Correction: Used a very fine sand paper and went over the scratches then put a sealer over the scratches.

Model#

Dlr Sub Hrs0.40

Sub Labor Amt\$56.00

Serial#

Appr Hrs0.40

Appr Labor Amt\$56.00

Notes
AUTHORIZED

Submitted	Labor Amt	\$182.00	Approved	Labor Amt	\$182.00
	Parts & Freight	\$8.72		Parts & Freight	\$8.72
	Total	\$190.72		Total	\$190.72

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.