

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12050

Date In:	15 MAY 25	Author:	MGRAY
Promised Date:	23 MAY 25	Stock No:	10848
:	:	Year:	2023
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	REFLECTION FW
:	MIDDLEBURY, IN	Model:	303RLS
Postal/Zip:	46540	Miles/Hrs:	:
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DROPPED 5/15
Purchased Date:	08 JUN 24	:	:
Delivery Date:	13 JUN 24	:	:
InService Date:	:	:	:
Serial#:	573FR3420P9923512	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
1       COMPLAINT:  WATER LEAK IN THE BATHROOM. SEEMS TO BE  W    1020    GRAND
        A SMALL LEAK BUT FLOOR SEEMS SOFT IN
        FRONT OF SHOWER NOW. CHECK OUT FOR DIAG
        AND ESTIMATE.
        CAUSE:      A soft spot in front of the toilet. I
                    air-tested the unit for leaks and there
                    aren't any. I ran water through the
                    toilet to check the flange seal and I
                    don't see any water. I removed the wall
                    in the front storage and I felt the
                    bottom of the floor and it's not soft
                    but it doesn't feel right either. I had
                    Matt walk around on the soft spot as I
                    watched from inside the storage
                    compartment and I can see the that
                    section of floor flexing a lot. I cut
                    the sub-floor material and the underside
                    of the floor is covered in white mold. I
                    cut a few more sections and the mold is
                    in different areas. We will have to see
                    what the manufacturer wants done.
        CORRECTION: ...
2       COMPLAINT:  THERE IS MOLDING IN SEVERAL PLACES      W    1020    GRAND
        COMING OFF, MOLDING ON DS SLIDE COMING
        APART, MOLDING BEHIND REFER, AND THE
        MOLDING IN THE BEDROOM, WILL TAPE PLACES
        NOTICED. USED GORILLA TAPE TO HOLD A
        LITTLE SO IT DID NOT GET DAMAGED IN
```

Continued on page 2

Work Order : 12050

```

*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
          TRAVEL.
CAUSE:   The DS facia board is coming off, ods
          baton strip to the right of the fridge,
          and the floor trim behind the bedroom
          door is coming off. I removed the facia
          board completely, removed all the nails,
          added a bead of silicone to the whole
          length of the facia header and nailed
          the facia board back on. I puttied the
          nail holes when I was done. There is no
          room for a nailer so after I removed the
          one piece of 3m tape the manufacturer
          used to hold the baton on i ran a bead
          of super glue down the baton and held it
          in place till the glue set. The
          manufacturer used one small screw to
          hold the floor trim on so I added more
          and longer screws to hold it in place.
          REQUEST .6
CORRECTION: Done.
3 COMPLAINT: FURNACE WHEN RUNNING IS BLOWING OUT      W      1020      GRAND
          STYROFOAM BALLS OUT OF VENTS. HAS
          VACUUMED OUT THE VENTS A FEW TIMES AND
          ARE STILL HAVING THEM BLOW OUT OF THE
          VENT.
CAUSE:   I ran the furnace for a little while and
          I saw a few pieces of foam come out.
          It's from when the unit was built and it
          will clear out eventually.  REQUEST .5
CORRECTION: Done.
4 COMPLAINT: NOTING - DO WE HAVE THE DOOR SHELVES FOR E      17367      GRAVE
          THE REFER? IF NOT PRICE TO ORDER.
CAUSE:   1001 CUSTOMER REQUESTED. It's not a part
          we keep in stock. We will have to order
          it.
CORRECTION: ...

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
1 Z990  MISC LABOUR CODE (EXTE JGK  W-1020  0.24  140.00  33.60
2 Z990  MISC LABOUR CODE (EXTE JGK  W-1020  1.00  140.00  140.00
3 Z990  MISC LABOUR CODE (EXTE JGK  W-1020  0.70  140.00  98.00
4 Z990  MISC LABOUR CODE (EXTE JGK  E-17367  0.10  130.00  13.00
1 Z990  MISC LABOUR CODE (EXTE JGK  W-1020  0.49  140.00  68.60
1 Z990  MISC LABOUR CODE (EXTE JGK  W-1020  0.27  140.00  37.80
3 Z990  MISC LABOUR CODE (EXTE JGK  W-1020  0.30  140.00  42.00

```

Continued on page 3

Work Order : 12050

```

*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
   1   SSE      SHOP SUPPLIES - EXTERNAL  W-1020    1.00    0.98    0.98
*****

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id           Parts    Labour    Sublet    Extras      Tax      Total
*****
E   17367             0.00     13.00     0.00     0.00     0.72     13.72
W   1020              0.00    420.00     0.00     0.98     0.00    420.98

      Totals          0.00    433.00     0.00     0.98     0.72    434.70

```

&k2S
&k0S