

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12057

Date In:	16 MAY 25	Author:	MGRAY
Promised Date:	31 DEC 25	Stock No:	11380
:	:	Year:	2025
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	FLAGSTAFF MICRO-LITE
:	WISCONSIN RAPIDS, WI	Model:	25FBLS
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB:8/6
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4TFLA28SD465337	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CEN     COMPLAINT:  CLEAN EXTERIOR- NEW                                I      PDI      PRE-D
        CAUSE:      NEED CLEAN
        CORRECTION:  CLEANED
NTTS    COMPLAINT:  NEW TRAVEL TRAILER STOCK PREP                    I      PDI      PRE-D
        CAUSE:      Done with prep
        CORRECTION:  Done.
ISR0    COMPLAINT:  INTERNAL STOCK REPAIR 01- water heater            W      1021    FORES
        was never plugged in from manufacturer.
        CAUSE:      Manufacturer never plugged in the water
        heater. Got it plugged in
        CORRECTION:  Done. REQ .20 LABOR WARR AUTH: .20
ISR0    COMPLAINT:  INTERNAL STOCK REPAIR 02- cabinet door            W      1021    FORES
        in bathroom under sink has a crack in
        it. Will need to be replaced.CABINET
        DOOR MEASURES H=26" X W=18".
        CAUSE:      Cracked cabinet door. I walked out on
        the lot, removed the cabinet door, and
        brought it inside. Our hinge jig doesn't
        line up with the one the manufacturer
        uses so I had to alter ours. I
        predrilled every hole to prevent anymore
        cracking and transferred the hardware.
        CORRECTION:  Done.
ISR0    COMPLAINT:  INTERNAL STOCK REPAIR 03- the cabinet on W        1021    FORES
        above the couch on the right side has a
        small crack in it at the hinge.
        CAUSE:      Small crack in right door above the
        couch. Put putty over it
```

Continued on page 2

Work Order : 12057

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
CORRECTION: Done. REQ .20 LABOR  WARR AUTH: .30
ISR0  COMPLAINT:  INTERNAL STOCK REPAIR 05- 3 of the 4      W      1021      FORES
        cabinet doors above the bed have small
        cracks in the door at the hinge
        CAUSE:      3 of the cabinets above the bed had
        small cracks in them from the screws. I
        put putty over them
        CORRECTION: Done. REQ .30 LABOR WARR AUTH: .30

```

```

*****
Job # Part No  Description      PARTS      Bill to  Qty      Price      Total
*****
ISR02 822011686 CABINET DOOR - SOP: SQUARE  W-1021      1      73.32      73.32

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
CEN CE          CLEAN EXTERIOR      EJ  I-PDI      0.63      70.00      44.10
NTTS RV1F-1A    NEW STOCK PREP      EG  I-PDI      0.41      70.00      28.70
NTTS RV1F-1A    NEW STOCK PREP      EG  I-PDI      0.96      70.00      67.20
NTTS RV1F-1A    NEW STOCK PREP      EG  I-PDI      0.49      70.00      34.30
NTTS RV1F-1A    NEW STOCK PREP      EG  I-PDI      1.34      70.00      93.80
NTTS RV1F-1A    NEW STOCK PREP      EG  I-PDI      0.93      70.00      65.10
NTTS RV1F-1A    NEW STOCK PREP      EG  I-PDI      0.26      70.00      18.20
NTTS RV1F-1A    NEW STOCK PREP      EG  I-PDI      0.11      70.00      7.70
ISR01 Z991      MISC LABOUR CODE (INTE EG  W-1021      0.20      140.00      28.00
ISR02 Z991      MISC LABOUR CODE (INTE JGK W-1021      0.36      140.00      50.40
ISR03 Z991      MISC LABOUR CODE (INTE EG  W-1021      0.30      140.00      42.00
ISR05 Z991      MISC LABOUR CODE (INTE EG  W-1021      0.30      140.00      42.00
ISR02 Z991      MISC LABOUR CODE (INTE JGK W-1021      0.04      140.00      5.60

```

```

*****
Job #  Excode      Description      EXTRAS      bill to  Qty      Price      Total
*****
ISR01 SSE          SHOP SUPPLIES - EXTERNAL  W-1021      1.00      0.00      0.00
ISR02 FRT          FREIGHT      W-1021      1.00      18.81      18.81

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I      PDI          0.00      359.10      0.00      0.00      0.00      359.10
W      1021          73.32      168.00      0.00      18.81      0.00      260.13

Totals      73.32      527.10      0.00      18.81      0.00      619.23

```

&k2S

Continued on page 3

Work Order : 12057

&k0S