

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 12057

Date In: 16 MAY 25	Author: MGRAY
Promised Date: 31 DEC 25	Stock No: 11380
:	Year: 2025
Customer Name: 1000 - GREENEWAY RV SA	Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT	Brand: FLAGSTAFF MICRO-LITE
: WISCONSIN RAPIDS, WI	Model: 25FBL5
Postal/Zip: 54494	Miles/Hrs: 0
Phone#(res): 800-758-2272	Exterior Color:
Phone#(bus):	Unit Type: TT-TRAVEL TRAILER
Cell Phone:	License#:
Email: NONE	Tag#:
Purchased Date:	:
Delivery Date:	:
InService Date:	:
Serial#: 4X4TFLA28SD465337	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CEN     CLEAN EXTERIOR- NEW                I      PDI      PRE-D
NTTS    COMPLAINT: NEW TRAVEL TRAILER STOCK PREP  I      PDI      PRE-D
        CAUSE: Done with prep
        CORRECTION: Done.
ISR0    COMPLAINT: INTERNAL STOCK REPAIR 01- water heater  W      1021    FORES
        was never plugged in from manufacturer.
        CAUSE: Manufacturer never plugged in the water
        heater. Got it plugged in
        CORRECTION: Done. REQ .20 LABOR
ISR0    COMPLAINT: INTERNAL STOCK REPAIR 02- cabinet door  W      1021    FORES
        in bathroom under sink has a crack in
        it. Will need to be replaced.
        CAUSE: CRACKED FROM MANUFACTURER
        CORRECTION: R&R CABINET DOOR REQ .40 LABOR
ISR0    COMPLAINT: INTERNAL STOCK REPAIR 03- the cabinet on W      1021    FORES
        above the couch on the right side has a
        small crack in it at the hinge.
        CAUSE: Small crack in right door above the
        couch. Put putty over it
        CORRECTION: Done. REQ .20 LABOR
ISR0    COMPLAINT: INTERNAL STOCK REPAIR 05- 3 of the 4  W      1021    FORES
        cabinet doors above the bed have small
        cracks in the door at the hinge
        CAUSE: 3 of the cabinets above the bed had
        small cracks in them from the screws. I
        put putty over them
        CORRECTION: Done. REQ .30 LABOR
*****
```

Continued on page 2

Work Order : 12057

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
CEN CE          CLEAN EXTERIOR          I-PDI    0.00    70.00    0.00
NTTS RV1F-1A   NEW STOCK PREP          EG      I-PDI    0.41    70.00    28.70
NTTS RV1F-1A   NEW STOCK PREP          EG      I-PDI    0.96    70.00    67.20
NTTS RV1F-1A   NEW STOCK PREP          EG      I-PDI    0.49    70.00    34.30
NTTS RV1F-1A   NEW STOCK PREP          EG      I-PDI    1.34    70.00    93.80
ISR01 Z991      MISC LABOUR CODE (INTE EG W-1021    0.50   140.00    70.00
ISR02 Z991      MISC LABOUR CODE (INTE      W-1021    0.00   140.00     0.00
NTTS RV1F-1A   NEW STOCK PREP          EG      I-PDI    0.93    70.00    65.10
ISR03 Z991      MISC LABOUR CODE (INTE EG W-1021    0.50   140.00    70.00
NTTS RV1F-1A   NEW STOCK PREP          EG      I-PDI    0.26    70.00    18.20
ISR05 Z991      MISC LABOUR CODE (INTE EG W-1021    0.50   140.00    70.00
NTTS RV1F-1A   NEW STOCK PREP          EG      I-PDI    0.11    70.00     7.70
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ISR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021  1.00  0.00  0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
I      PDI          0.00   315.00  0.00   0.00   0.00   315.00
W      1021         0.00   210.00  0.00   0.00   0.00   210.00

Totals          0.00   525.00  0.00   0.00   0.00   525.00
*****
```

&k2S
&k0S