

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497  
 GREENEWAY INC  
 DBA GREENEWAY RV SALES & SERVICE  
 8220 STATE HWY 13 SOUTH  
 WISCONSIN RAPIDS, WI 54494  
 USA

CLAIM STATUS Paid  
 CLAIM 2393138  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 4X4TFLA28SD465337  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 010 / 010B  
 ITEM # FLT25FBLS  
 DEALER RO # 12057  
 CLAIM START DATE 08/06/2025  
 CLAIM END DATE 09/02/2025

Labor rate: \$140.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

Line# 1      **Operation Code**      **Operational Description**  
 70-167-24-00-002001      Water Heater Door - Appliances/Water Heater (Suburban)/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-08-06 16:28:12 :: Complaint: Water heater was never plugged in from manufacturer. Cause: Manufacturer never plugged in the water heater. Correction: Plugged in water heater. Additional Note : greeneway@dealer-advisors.com, 2025-08-06 16:30:07 :: No repair code.

Model# 1	Dlr Sub Hrs	0.20	Sub Labor Amt	\$28.00
Serial# 1	Appr Hrs	0.20	Appr Labor Amt	\$28.00

**Notes**  
 We have updated the repair code to a more appropriate one based on the identified root cause of this repair request

### Labor

Line# 2      **Operation Code**      **Operational Description**  
 30-100-01-00-001035      Cabinet Door - Interior/Cabinetry/Replace/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-08-06 16:30:52 :: Complaint: Cabinet door in bathroom under sink has a crack in it. Cause: Cracked from manufacturer. Correction: R&R cabinet door.

Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$56.00
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$56.00

**Notes**  
 authorized to replace pending dimensions of the door.

### Part

Line# 1      **Item #**      **Description**  
 F100411686      CABINET DOOR - SOP: SQUARE - SEDONAWOOD - 18" X 26" - V# 636602

<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>		
Sub Qty 1.00	Sub Dlr Price \$73.32	Sub Freight \$18.81		
Appr Qty 1.00	Appr Dlr Price \$73.32	Appr Freight \$18.81		

**Notes**

### Labor

Line# 3      **Operation Code**      **Operational Description**  
 30-100-24-00-001046      Cabinet Door - Interior/Cabinetry/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-08-06 16:31:54 :: Complaint: The cabinet above the couch on the right side has a small crack in it at the hinge. Cause: Small crack in the right door above the couch from factory. Correction: Put putty over it.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$42.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$42.00

Notes

Labor  
Line# 4

Operation Code

30-100-24-00-001046

Operational Description

Cabinet Door - Interior/Cabinetry/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-08-06 16:32:54 :: Complaint: 3 of the 4 cabinet doors above the bed have small cracks in the door at the hinges. Cause: Cracks from the screws installed at factory. Correction: Put putty over them.

Model#

Dlr Sub Hrs

0.30

Sub Labor Amt \$42.00

Serial#

Appr Hrs

0.30

Appr Labor Amt \$42.00

Notes

---

Submitted

Labor Amt \$168.00  
Parts & Freight \$92.13  
Total \$260.13

Approved

Labor Amt \$168.00  
Parts & Freight \$92.13  
Total \$260.13

---

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

---

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.