

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12064

Date In: 19 MAY 25 Author: DLUCAS
Promised Date: 05 JUN 25 Stock No: 11104
: Year: 2024
Customer Name: 15706 - TEIGLAND, SCOT Manufacturer: FOREST RIVER
Address: 1405 RAMONA DRIVE Brand: PUMA TT
: MT. PLEASANT, WI Model: 31RLQS
Postal/Zip: 53406 Miles/Hrs: 0
Phone#(res): (262) 930-7171 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: STEIGLAND@ATT.NET Tag#:
Purchased Date: 25 MAY 24 :
Delivery Date: 07 JUN 24 :
InService Date: :
Serial#: 4X4TPUG23RP101345 :

Job # Description JOB INFORMATION Type Bill To

SC SERVICE CALL TO WILSON LAKE CAMPGROUND, WILD ROSE E 15706 TEIGL
SITE 220
1 COMPLAINT: CUSTOMER CONCERNED WITH AC UNIT NOT W 1021 FORES
COOLING, CANNOT HEAR THE COMPRESSOR KICK
ON AT ANY POINT.
CAUSE: the rear ac in living room amp draw of
9.2. on compressor leak in system
outside temp 79 degrees inside temp 79
degrees coming out of ac. the ac in not
cooling after 20 mins will need a new
ac
CORRECTION: Will need a new ac..... AC NEEDED ON
PARTS HOLD FOR WARRANTY REQUEST 2 HOURS
OF LABOR
2 COMPLAINT: CUSTOMER WOULD LIKE FURNACE LOOKED AT, W 1021 FORES
WHEN RUNNING FURNACE IS NOT GETTING ANY
AIRFLOW OUT OF BATHROOM VENT, ALSO ONE
OF THE 3 IN LIVING AREA DOES NOT BLOW
CAN PUT TOILET PAPER OVER IT AND WONT
BLOW PAPER.
CAUSE: there's no blockage what I found is
there so much good airflow it blow out
the ends so I restricted and of vent on
end end to slow airflow down now coming
out of bathroom vent and middle vent
closes to furnace customer can try vents
where you can partly close to slow down
airflow pics and measurements taken

Continued on page 2

Work Order : 12064

```
*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CORRECTION: try vents that you can control airflow
            but there's no blockage.... NEED
            MANUFACTURER ADVISEMENT AS FR DOES NOT
            OFFER VENTS WITH DAMPENERS FOR THIS UNIT
            REQUEST .50 HOURS OF LABOR
*****
```

```
*****
Job # Part No Description      PARTS      Bill to Qty Price Total
*****
1      8220ACB GE RV AC 15K BTU BLACK      W-1021 0 807.74 0.00
*****
```

```
*****
Job# Lab Code Description      LABOUR      Mech Bill to Hrs Rate Total
*****
1 DIAG      DIAGNOSTICS      JS W-1021 1.00 140.00 140.00
2 DIAG      DIAGNOSTICS      JS W-1021 1.00 140.00 140.00
*****
```

```
*****
Job # Excode Description      EXTRAS      bill to Qty Price Total
*****
SC SSE      SHOP SUPPLIES - EXTERNAL      E-15706 1.00 0.00 0.00
SC SC      SERVICE CALL      E-15706 38.00 3.75 142.50
*****
```

```
*****
BILLINGS SUMMARY
Type Bill Id      Parts Labour Sublet Extras Tax Total
*****
E 15706      0.00 0.00 0.00 142.50 7.85 150.35
W 1021      0.00 280.00 0.00 0.00 0.00 280.00

Totals      0.00 280.00 0.00 142.50 7.85 430.35
*****
```

&k2S
&k0S