



GE APPLIANCES
a Haier company



Air Conditioner Performance Check-List for Warranty Coverage

For Technical Assistance Call: 800-772-7262

Once Completed Email Form To:

OEM Claims Email: RecreationalLiving-warranty@geappliances.com

Dealer Claims Email: NTRemergingResources@geappliances.com

Incomplete or inaccurate information will delay processing.

Dealer Name: Greenway Rv

Dealer Account #

Dealer Phone: 75-325-5170

Dealer Contact:

Dealer Email:

Customer Date of Purchase -or -Stock Unit: 06/10/24

Customer Name: Teiglan, Scott

RV Manufacturer & Model: Forest River Puma Year of Coach: 2024

Complete RV VIN: 4X4TPUG23RP101345

If Replacement Product or Part is Needed, Verify Ship to Address

Dealer PO#: 12064

Shipping Address: 3220 Highway 13 So

City: Wisconsin Rapids State: WI

Zip Code: 54494

Air Conditioner Model #: ARC15AACBL2

Air Conditioner Serial #: HT103220R

Part Number of the Control Box:

Is a GE T-Stat Being Used? White or Black? Yes, Black

Date of Purchase or Indication of Stock Unit: 06/10/24

Diagnostic Information

Compressor Running? Yes

AC Voltage: 120V

Nature of Complaint:

Ac unit not cooling

If You Have A No Cool AC: After 15 Minutes of Running and with Shroud Cover On (Outdoor Temp Must be At Least 65 Degrees F)

AMP Draw on Black Compressor Wire: 9.2

Ambient Roof Temperature: 79°

Return/Intake Temperature: 79°

Discharge/Output Temperature: 79°

If There Is A Visible Leak In the Sealed System, Please Include a Picture Of the Leak

no visible leak