



# Warranty Claim Form

Date: 6/27/2025

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States  
Ph. 715-325-5170  
mail@greenwayrv.com

### General Information

573FM4124SBB04113  
Momentum 351MS  
Retail Purchase Date: null  
Work Started: 6/2/2025  
Work Completed: 6/2/2025

Claim Status: Paid  
Dealer Work Order #: 12065B  
Unit Offline Date: 4/22/2025

Claim #: 905935  
Labor: \$140.00  
Parts: \$0.00  
Shipping: \$0.00  
Total: \$140.00

Notes:

### Dealer Information

### Customer Information

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States

715-325-5170  
mail@greenwayrv.com  
Approved Labor Rate: \$140.00

### Operation Line # 1

*Flat Rate Code:* 620003 Floor Covering - R&R Linoleum (per In. ft., *Fault Code:* Improper Installation/Build including attachments)

*Problem:* Lino gouges near stove. Found screw on floor after opening slide room.

*Hours:* 1

*Cause:* Screw left by manufacturer and it damaged the floor.

*Amount:* 140.00

*Remedy:* Used floor sealant and a touch of putty put beneath scrape then rolled out the floor well.  
Put a dab of sealant over the top.

*Sublet Repairs:* \$0.00

*Manufacturer #:*

*Model #:*

*Serial #:*