

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12066

Date In:	19 MAY 25	Author:	MGRAY
Promised Date:	08 AUG 25	Stock No:	10473
:	:	Year:	2023
Customer Name:	16532 - BECKER, CHRIST	Manufacturer:	FOREST RIVER
Address:	400 WISCONSIN ST	Brand:	FLAGSTAFF SUPER-LITE T
:	WAUPACA, WI	Model:	29RBS
Postal/Zip:	54981	Miles/Hrs:	0
Phone#(res):	(715) 412-0958	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	db: 7/7
Purchased Date:	09 MAY 24	:	:
Delivery Date:	23 MAY 24	:	:
InService Date:	:	:	:
Serial#:	4X4TFLE23PZ185412	:	:

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - Water is leaking W 1021 FORES
 from under the sink. There is water
 damage on the kitchen cupboard and
 flooring.
 CAUSE: I ran hot and cold water through the
 water lines and I'm not seeing anything
 leaking. I filled both sink tubs to
 check the drains and still no leaks. I
 left the lines pressurized for three
 days and no leaks have shown up yet.
 There was a leak of some sort at one
 time because two styles were damaged.
 Two styles will need to be replaced and
 we will need a sheet of paneling. The
 manufacturer has a lot of staples in the
 paneling so the chances of it coming off
 in one piece are pretty slim. 5-6 hours
 to fix depending on how everything comes
 apart and if I have to wrap the styles
 myself with the cheap wrap that creases
 from air touching it that the
 manufacturer sends. I removed all the
 drawers from the kitchen cabinet and as
 I was looking at it I saw a shelf that
 was in the way of removing the panel
 that I didn't see before. I removed the
 furnace duct and outlets from the panel
 and I very carefully started popping the

Continued on page 2

Work Order : 12066

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
panel loose from the styles. I got the
panel loose to the shelf, removed all
the staples, pulled the screws that are
going into the floor and counter top and
pried them loose. I got the style out,
cut the new one to size and put it in
place. I put everything back together
and puttied the holes.

CORRECTION: Done.
WARR COMPLAINT: WARRANTY REPAIR 2 - CMR WAS FLUSHING      W      1021    FORES
BLACK TANK AND WATER STARTED GUSHING OUT
OF THE OUTDOOR SHOWER FAUCET. CHECK OUT
FOR DIAG.

CAUSE: Faulty check valve. I hooked up the
black tank flush, turned the water on,
went inside and I could see water coming
out the top of the check valve. I turned
the water off, drained the lines,
disconnected the valve, hooked the new
valve up, and turned the water on to
test it and the leak stopped. I dried up
the area the best I could and I turned a
blower on to help dry everything out.
After everything dried out I checked it
again and the leaks stopped.

CORRECTION: Done.
1 COMPLAINT: AWNING WE REPLACED NOW DOES NOT WANT TO I      PD      GOODW
COME IN OR OUT PROPERLY. CHECK OUT FOR
DIAG.

CAUSE: NPF. I ran the awning in and out
several times and everything is working
properly.

CORRECTION: Done.
WARR COMPLAINT: WARRANTY REPAIR 3 - SHOWER IN MAIN      W      1021    FORES
BATHROOM IS LEAKING.

CAUSE: NPF with the showermizer but when I was
checking for leaks I could hear water
dripping under the bathroom sink and
when I looked inside I could see the hot
and cold fittings were leaking. I
drained the water lines, disconnected
the hot and cold fittings, checked the
seals and they're good. I put thread
tape on the fittings, tightened them
down and turned the water on to test it.
I ran hot and cold water through the
lines and the leaks stopped.

CORRECTION: Done.

```

Continued on page 3

Work Order : 12066

```
*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 756815001472 VACUUM BREAKER / CHECK V W-1021      1      33.36      33.36
WARR0 82203025      STILE - 13N-1: SQUARE ED W-1021      1      15.18      15.18
WARR0 822082994      PANELING - 5S-9: LAUAN - W-1021      1      37.06      37.06
WARR0 149105        NOVAFLEX SEALANT SANDSTO W-1021      1      8.89      8.89
*****
```

```
*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.38      140.00      53.20
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.12      140.00      16.80
ARR01 WARR      MANUFACTURER WARRANTY JGK W-1021      0.50      140.00      70.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.33      140.00      46.20
ARR02 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.17      140.00      23.80
   1 DIAG      DIAGNOSTICS              JGK I-PD      0.83      70.00      58.10
   1 DIAG      DIAGNOSTICS              JGK I-PD      0.17      70.00      11.90
ARR03 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR03 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.44      140.00      61.60
ARR03 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.06      140.00      8.40
ARR01 WARR      MANUFACTURER WARRANTY JGK W-1021      0.00      140.00      0.00
ARR01 WARR      MANUFACTURER WARRANTY JGK W-1021      0.50      140.00      70.00
ARR01 WARR      MANUFACTURER WARRANTY JGK W-1021      0.00      140.00      0.00
ARR01 WARR      MANUFACTURER WARRANTY JGK W-1021      0.00      140.00      0.00
*****
```

```
*****
Job #  Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
   1   SSE          SHOP SUPPLIES - EXTERNAL I-PD      1.00      0.00      0.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I   PD            0.00      70.00      0.00      0.00      0.00      70.00
W   1021          94.49      350.00      0.00      0.00      0.00      444.49

Totals          94.49      420.00      0.00      0.00      0.00      514.49
*****
```

&k2S

&k0S