



Warranty Claim Form

Date: 6/27/2025

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenewayrv.com

General Information

573FS3627SAA20575
Solitude 310GK
Retail Purchase Date: null
Work Started: 6/5/2025
Work Completed: 6/5/2025

Claim Status: Paid
Dealer Work Order #: 12094C
Unit Offline Date: 12/11/2024

Claim #: 905937
Labor: \$140.00
Parts: \$0.00
Shipping: \$0.00
Total: \$140.00

Notes:

Dealer Information

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenewayrv.com
Approved Labor Rate: \$140.00

Customer Information

Operation Line # 1

Flat Rate Code: 570023 Wall Bottom Edge Molding - Repair *Fault Code:* Improper Installation/Build

Problem: DS slide two screw head have come off on bottom of screw trim.

Hours: 1

Cause: Screws were over torqued by manufacturer.

A m o u n t :
140.00

Remedy: Removed the screws on both side of slide from the trim at the bottom of the slide. As we were *S u b l e t* doing this, we found that most of the screws were broken off. Used pliers and by hand unscrewed the *Repairs:* \$0.00 portion that was broken off inside the wall on 9 screws. Cleaned off silicone from wall, reinstalled screws and sealed over the top edge of trim.

Manufacturer #:

Model #:

Serial #: