

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12096

Date In: 23 MAY 25 Author: MGRAY
Promised Date: 31 DEC 25 Stock No: 11359
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN
Address: 8220 STATE HWY 13 SOUT Brand: IMAGINE XLS
: WISCONSIN RAPIDS, WI Model: 22MLE
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: DB: 8/6
Purchased Date: 11 AUG 25 :
Delivery Date: 19 AUG 25 :
InService Date: :
Serial#: 573TE2624S3443488 :

Job #	Description	JOB INFORMATION	Type	Bill To
CEN	CLEAN EXTERIOR- NEW		I	PDI PRE-D
NTTS	COMPLAINT: NEW TRAVEL TRAILER STOCK PREP		I	PDI PRE-D
	CAUSE: New unit			
	CORRECTION: Complete prep done Bedspread on order on its own warranty line			
WARR	COMPLAINT: WARRANTY REPAIR 1 - screen on vent in kitchen is loose		W	1020 GRAND
	CAUSE: Mfg improper install			
	CORRECTION: I thought the tens were broken but after pushing I found I was able to push each tab in and now the screen is good			
WARR	COMPLAINT: WARRANTY REPAIR 2 - 7 screw heads are popping up around vents on roof and 2 bubbles in dicor on roof		W	1020 GRAND
	CAUSE: Mfg			
	CORRECTION: Cleaned areas well then dicored over the screw heads and popped bubbles REQ .30 HOURS LABOR WARR AUTH: .20			
WARR	COMPLAINT: WARRANTY REPAIR 3 - Trim above loveseat has a rather large gap in it		W	1020 GRAND
	CAUSE: Mfg			
	CORRECTION: I filled the gap with putty REQ .10 LABOR WARR AUTH: .10			
WARR	COMPLAINT: WARRANTY REPAIR 4 - backside of bed covering which was sealed in a bag has stains so it was put into the bag dirty		W	1020 GRAND
	CAUSE: Mfg stains on back of bed covering it was put into sealed bag this way. ORDER			

Continued on page 2

Work Order : 12096

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                NEW BED COVERING PIC OF TAGS AND THE
                                STAINS TAKEN
CORRECTION: ..... REQ .20 HOURS LABOR
WARR AUTH: .20 COMPLETE
*****
```

```
*****
Job # Part No  Description                PARTS                Bill to  Qty  Price  Total
*****
WARR0 822084095 BEDSPREAD 80 X 90 RL HONEYC W-1020 1 86.42 86.42
*****
```

```
*****
Job# Lab Code Description                LABOUR Mech Bill to  Hrs  Rate  Total
*****
CEN CE CLEAN EXTERIOR I-PDI 0.00 70.00 0.00
NTTS RV1F-1A NEW STOCK PREP HOD I-PDI 2.57 70.00 179.90
NTTS RV1F-1A NEW STOCK PREP HOD I-PDI 0.94 70.00 65.80
NTTS RV1F-1A NEW STOCK PREP HOD I-PDI 0.00 70.00 0.00
NTTS RV1F-1A NEW STOCK PREP HOD I-PDI 0.71 70.00 49.70
NTTS RV1F-1A NEW STOCK PREP HOD I-PDI 0.28 70.00 19.60
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.40 140.00 56.00
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.07 140.00 9.80
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.02 140.00 2.80
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.11 140.00 15.40
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.20 140.00 28.00
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.10 140.00 14.00
ARR04 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.10 140.00 14.00
ARR04 WARR MANUFACTURER WARRANTY JS W-1020 0.10 140.00 14.00
*****
```

```
*****
Job # Excode Description                EXTRAS                bill to  Qty  Price  Total
*****
ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1020 1.00 0.00 0.00
ARR04 FRT FREIGHT W-1020 1.00 24.37 24.37
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
I PDI 0.00 315.00 0.00 0.00 0.00 315.00
W 1020 86.42 154.00 0.00 24.37 0.00 264.79
*****
Totals 86.42 469.00 0.00 24.37 0.00 579.79
*****
```

&k2S
&k0S