

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 12116B

Date In: 02 JUN 25 Author: KOTT  
Promised Date: 05 JUN 25 Stock No: 11248  
: Year: 2025  
Customer Name: 17722 - HINK, JUSTIN Manufacturer: FOREST RIVER  
Address: 17010 51ST AVENUE Brand: PUMA DESTINATION  
: CHIPPEWA FALLS, WI Model: 38RLB  
Postal/Zip: 54729 Miles/Hrs: 0  
Phone#(res): 715-312-0149 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: HINKJUS32@HOTMAIL.COM Tag#: st: 6/5@11  
Purchased Date: 23 MAY 25 :  
Delivery Date: 05 JUN 25 :  
InService Date: :  
Serial#: 4X4TPUP28SP104280 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
WARR COMPLAINT: WARRANTY REPAIR 1 - There is some sort W 1021 FORES  
of white residue on the sliding door  
lock.  
CAUSE: 1000 DEFECT FROM MANUFACTURER. I cleaned  
it off with solvent and a putty stick.  
CORRECTION: Done. REQUEST .30 HOURS LABOR  
WARR COMPLAINT: WARRANTY REPAIR 2 - There is a piece of W 1021 FORES  
tape hanging down off the ODS subfloor.  
CAUSE: 1000 DEFECT FROM MANUFACTURER. I removed  
the rest of the piece of tape and filled  
the gap with silicone.  
CORRECTION: Done. REQUEST .20 HOURS OF LABOR  
WARR COMPLAINT: WARRANTY REPAIR 3 - There are a bunch of W 1021 FORES  
ants in the unit along the DS slide  
floor.  
CAUSE: 1000 DEFECT FROM MANUFACTURER. I  
bug-bombed the unit. It took me .3 to  
complete  
CORRECTION: Done REQUEST .30 HOURS OF LABOR  
WARR COMPLAINT: WARRANTY REPAIR 4 - The top of the W 1021 FORES  
bedroom and bathroom doors are marked  
up.  
CAUSE: 1000 DEFECT FROM MANUFACTURER. I touched  
up both the doors with a paint pen.  
CORRECTION: Done. REQUEST .40 HOURS OF LABOR  
WARR COMPLAINT: WARRANTY REPAIR 5 - The inside of the W 1021 FORES  
microwave is scratched.  
CAUSE: 1000 DEFECT FROM MANUFACTURER. We will

Continued on page 2

Work Order : 12116B

```
*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                have to order a new microwave.
WARR    CORRECTION: ... PLEASE NOTE WITH THE MANUFACTURER-
COMPLAINT: WARRANTY REPAIR 6 - There is a brown      W    1021  FORES
                stain on the sliding door curtain.
CAUSE:      1000 DEFECT FROM MANUFACTURER. I went to
                the cleaner cart and got a fabric
                cleaner and I cleaned the stains out.
WARR    CORRECTION: Done. REQUEST .30 HOURS OF LABOR
COMPLAINT: WARRANTY REPAIR 7 - The sealant along      W    1021  FORES
                the baton strip on the ceiling is
                cracked.
CAUSE:      1000 DEFECT FROM MANUFACTURER. I re
                sealed the edge of the baton strip.
WARR    CORRECTION: Done. REQUEST .30 HOURS OF LABOR
COMPLAINT: WARRANTY REPAIR 8 - There are white      W    1021  FORES
                scuff marks on the bunk room slide trim.
CAUSE:      1000 DEFECT FROM MANUFACTURER. I cleaned
                them off with solvent and a rag.
WARR    CORRECTION: Done. REQUEST .20 HOURS OF LABOR
COMPLAINT: WARRANTY REPAIR 9 - The facia board on    W    1021  FORES
                the bunk room slide is popping off.
CAUSE:      1000 DEFECT FROM MANUFACTURER. I nailed
                it back on and puttied the holes.
WARR    CORRECTION: Done. REQUEST .60 HOURS OF LABOR
COMPLAINT: WARRANTY REPAIR 10 - The sealant is      W    1021  FORES
                cracked on the bottom front corner of
                the DS slide.
CAUSE:      1000 DEFECT FROM MANUFACTURER. I cleaned
                and re sealed the problem area.
WARR    CORRECTION: Done. REQUEST .20 HOURS OF LABOR
COMPLAINT: WARRANTY REPAIR 11 - There is a section  W    1021  FORES
                of eturnabon tape on the bunk room slide
                roof that isn't sticking to anything.
CAUSE:      1000 DEFECT FROM MANUFACTURER. I put a
                new piece of eturnabon tape over the top
                of the existing one.
WARR    CORRECTION: Done. REQUEST .60 HOURS OF LABOR
COMPLAINT: WARRANTY REPAIR 12 - FOUND ON PREP- THE  W    1021  FORES
                AC IS NOT COOLING CORRENTLY-
CAUSE:      NPF. It must have been a bad power cord
                in the wash line. I brought the unit up
                to the building, plugged it in, turned
                the a/c on and after 15 minutes the a/c
                dropped 25 degrees.
CORRECTION: Done.
```

Continued on page 3

Work Order : 12116B

```
*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 149100      NOVAFLEX SEALANT ANTIQUE W-1021      1      10.01      10.01
WARR1 891991000533 ETERNABOND WHITE      W-1021      6      1.86      11.16
*****
```

```
*****
Job# Lab Code Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.30      140.00      42.00
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.20      140.00      28.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR03 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.50      140.00      70.00
ARR03 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR04 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.50      140.00      70.00
ARR04 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR05 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.50      140.00      70.00
ARR05 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR06 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.50      140.00      70.00
ARR06 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR07 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.50      140.00      70.00
ARR07 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR08 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.50      140.00      70.00
ARR08 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR09 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.50      140.00      70.00
ARR09 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR10 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.50      140.00      70.00
ARR10 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR11 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.50      140.00      70.00
ARR11 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR12 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.50      140.00      70.00
*****
```

```
*****
Job # Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR01 SSE      SHOP SUPPLIES - EXTERNAL W-1021      1.00      0.00      0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      21.17      770.00      0.00      0.00      0.00      791.17
*****
Totals      21.17      770.00      0.00      0.00      0.00      791.17
*****
```

&k2S  
&k0S