

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12148B

Date In:	03 JUN 25	Author:	KOTT
Promised Date:	12 JUN 25	Stock No:	11409
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	403LFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	30 APR 25	:	:
Delivery Date:	12 JUN 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS24TP105967	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
1	COMPLAINT:	FOUND AT THE TIME OF DROP OFF/DAF- THE W 1021 FORES		
		ODS REAR SLIDE OUT WILL NOT CLOSE- TECH		
		THINKS IT MAY BE A SLIDE OUT SWITCH-		
		NEEDS TO BE DIAGNOSED-		
	CAUSE:	Bad slide motor. I put a battery on the		
		unit, plugged it in, hit the switch and		
		the slide made a noise, and that's it. I		
		verified that the battery was given out		
		12 volts and it is. I pulled the monitor		
		panel out and verified the incoming and		
		outgoing voltage at the switch. I		
		partially dropped the underbelly and		
		checked the voltage at the motor and		
		it's good. I hooked a battery directly		
		up to the motor and it didn't make a		
		sound. We need a new slide motor. The ID		
		tag for the motor is on the top side of		
		the motor so I had to push the sub-floor		
		up and take multiple pictures of the		
		tag. I tucked the underbelly back up and		
		put the monitor panel back in place. I		
		had to run the slide manually. The		
		manufacturer sent the wrong motor. We		
		need to re-order. Add .3 for my time		
		putting the old motor back in so the		
		unit can be delivered. We got the new		
		motor in at the last second so I		
		installed and tested it. Bad slide		

Continued on page 2

Work Order : 12148B

Job #	Description	JOB INFORMATION	Type Bill To
-------	-------------	-----------------	--------------

motor. I put a battery on the unit,
 plugged it in, hit the switch and the
 slide made a noise, and that's it. I
 verified that the battery was given out
 12 volts and it is. I pulled the monitor
 panel out and verified the incoming and
 outgoing voltage at the switch. I
 partially dropped the underbelly,
 checked the voltage at the motor and
 it's good. I hooked a battery directly
 up to the motor and it didn't make a
 sound. We need a new slide motor. The ID
 tag for the motor is on the top side of
 the motor so I had to push the sub-floor
 up and take multiple pictures of the
 tag. I tucked the underbelly back up and
 put the monitor panel back in place. I
 had to run the slide in manually.

CORRECTION: Done. ...

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
-------	---------	-------------	-------	---------	-----	-------	-------

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
------	----------	-------------	--------	------	---------	-----	------	-------

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
-------	--------	-------------	--------	---------	-----	-------	-------

Continued on page 3

Work Order : 12148B

&k2S
&k0S