



Warranty Claim Form

Date: 6/19/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TT2526T8839465
Transcend 20MKX
Retail Purchase Date: null
Work Started: 6/3/2025
Work Completed: 6/3/2025

Claim Status: Paid
Dealer Work Order #: 12150B
Unit Offline Date: 5/19/2025

Claim #: 904324
Labor: \$56.00
Parts: \$0.00
Shipping: \$0.00
Total: \$56.00

Notes:

Dealer Information

Customer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Operation Line # 1

Flat Rate Code: 560009 Entry Door - R&R or Adjust Striker Plate/ *Fault Code:* Improper Installation/Build Catch

Problem: The entry door on the unit will not close.

Hours: .4

Cause: Entrance door is hard to close due to the striker plate being misaligned.

Amount: 56.00

Remedy: Adjusted the striker plate on the jam outward to get the door to close properly. *No adjust code for striker plate.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: