

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12150C

Date In:	28 AUG 25	Author:	MGRAY
Promised Date:	31 DEC 25	Stock No:	11276
:	:	Year:	2026
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	GRAND DESIGN
Address:	8220 STATE HWY 13 SOUT	Brand:	TRANSCEND XPLO
:	WISCONSIN RAPIDS, WI	Model:	20MKX
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 8/29
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	573TT2526T8839465	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Mirrors on cabinet  W    1020    GRAND
        doors next to bed rattle badly when
        opening
        CAUSE:      No clips to hold mirror in place or
        silicone to buffer the rattle of mirror
        glass when opening or closing the doors
        CORRECTION: I used clear silicone and silicone
        around the interior of cabinet where the
        mirror is the mirror now is not rattling
        when opening the cabinet doors
WARR    COMPLAINT:  WARRANTY REPAIR 3 - bath slider door is  W    1020    GRAND
        tight at bottom and does not touch at
        the top
        CAUSE:      Mfg installed uneven
        CORRECTION: Removed the header to access the gliders
        adjusted them as much as possible much
        more even spacing and unable to see
        into bathroom with door closed
        REQUEST: .20 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 2 - water heater seam is W    1020    GRAND
        not sealed
        CAUSE:      Mfg forgot to seal seam on water heater
        CORRECTION: Cleaned seam then used clear silicone to
        seal Pic taken of model and serial and
        brand REQUEST: .20 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 4 - the bed cover has a  W    1020    GRAND
        bleached Mark on it
        CAUSE:      Cheap China made polyester bed cover
*****
```

Continued on page 2

Work Order : 12150C

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                that has a bleach Mark on it
CORRECTION: Please order new bed cover I took pic of
                the only tag on the fitted sheet
                REQUEST .20 HOURS OF LABOR
WARR    COMPLAINT: WARRANTY REPAIR 5 - the fan rattles and W    1020    GRAND
                is hitting vent screen above stove
CAUSE:      Misaligned fan blades
CORRECTION: I removed the screw that holds vent
                screen into place then gently pushed on
                back end of fan so it will not hit the
                screen ,I put screen back into place
                tested the blades no longer are hitting
                the screen works as it should REQUEST
                .40 HOURS OF LABOR
WARR    COMPLAINT: WARRANTY REPAIR 6 Mfg had done two lino W    1020    GRAND
                repairs in flooring , Note with mfg that
                it was noticed in case future customer
                notices
CAUSE:      Mfg had done 2 lino repairs in floor
                pics attached
CORRECTION: NOTE WITH MFG IF FUTURE CUSTOMER HAS A
                ISSUE OR NOTICES THIS PLEASE
WARR    COMPLAINT: WARRANTY REPAIR 8 - lino has a small W    1020    GRAND
                hole down to the subfloor
CAUSE:      Hole in lino from mfg
CORRECTION: I used brown putty to fill the small
                hole then I used sealer over the top of
                the putty REQUEST .30 HOURS OF LABOR

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.10  140.00  14.00
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.10  140.00  14.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.49  140.00  68.60
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.01  140.00  1.40
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.49  140.00  68.60
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.01  140.00  1.40
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.00  140.00  0.00
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00

```

```

*****
Job #  Excode   Description  EXTRAS      bill to  Qty  Price  Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1020  1.00  0.00  0.00

```

Continued on page 3

Work Order : 12150C

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1020	0.00	378.00	0.00	0.00	0.00	378.00
	Totals	0.00	378.00	0.00	0.00	0.00	378.00

&k2S
&k0S