

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 12172

Date In: 06 JUN 25	Author: KOTT
Promised Date: 25 DEC 25	Stock No: 11389
:	Year: 2025
Customer Name: 17732 - PRICE, DANNY	Manufacturer: GRAND DESIGN
Address: 8201 MORGAN LAKE RD P.	Brand: REFLECTION FW
: FENCE, WI	Model: 360FLS
Postal/Zip: 54120	Miles/Hrs: 0
Phone#(res):	Exterior Color:
Phone#(bus):	Unit Type: FW-FIFTH WHEEL
Cell Phone:	License#:
Email: doot19@gmail.com	Tag#: 8/12
Purchased Date: 30 MAY 25	:
Delivery Date: 11 JUL 25	:
InService Date:	:
Serial#: 573FR4022S9929980	:

```
*****
```

Job #	Description	JOB INFORMATION	Type	Bill To
1	COMPLAINT: SOLD COMPLETE PREP NEW FW		I	PDI PRE-D
	CAUSE: Sold complete prep			
	CORRECTION: Sold complete prep complete			
2	COMPLAINT: TOW: 2025 CHEVY SILVERADO 2500HD BC: Y	TP: Y HITCH:	I	DO DEALE
	CORRECTION: NOTING			
3	COMPLAINT: SUPER GLIDE HITCH PLR4500 W/CAPTURE	PLATE INCLUDED	I	DO DEALE
	CAUSE: Install superglue in factory location.			
	CORRECTION: Installed			
ST	COMPLAINT: SHOWTHRU&SHOWOUT SALESMAN: MARK		I	PDI PRE-D
	CAUSE: Showthru			
	CORRECTION: Showed customers there brand new camper and hooked them up and sent them down the road			
CIN	COMPLAINT: CLEAN INTERIOR- NEW		I	PDI PRE-D
	CAUSE: DIRTY			
	CORRECTION: CLEAN			
CEN	COMPLAINT: CLEAN EXTERIOR- NEW		I	PDI PRE-D
	CAUSE: DIRTY			
	CORRECTION: CLEAN			
4	COMPLAINT: LIPPERT RHINO BOX CAPTURE PLATE NWS# 8219.1723-PULLRITE# 331723		I	DO DEALE
	CAUSE: Camper needs capture plate			
	CORRECTION: Installed capture plate on camper			
WARR	COMPLAINT: Tail lights lens cracked		W	1020 GRAND
	CAUSE: Tail light lens is cracked Ring for ods tail light is cracked.			

Continued on page 2

Work Order : 12172

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: Need new lens for tail light Installed
new ring.
NFWS    COMPLAINT: need to calibrate auto leveling system   W    1020    GRAND
        IT IS NOT OPERATING CORRECTLY-
        CAUSE: Recalibrate auto leveling system.
        CORRECTION: Leveling system recalibrate. Tested
        good. REQUEST .50 HOURS OF LABOR
        warranty auth: .20 hours of labor
5      COMPLAINT: UNIT DOES NOT HAVE A POWER CORD-        W    1020    GRAND
        CAUSE: NO CORD FROM THE MANUFACTURER
        CORRECTION: NEED TO ORDER POWER CORD
MXGD    COMPLAINT: APPLY MAXXGUARD TO UNIT EXTERIOR AND        I    DOF    DEALE
        INTERIOR
        CAUSE: To Apply Interior and Exterior
        Protection Guard to Unit
        CORRECTION: Applied Interior and Exterior Protection
        Guard to Unit
MFP4    COMPLAINT: MOUSE FREE PRO30-40 FT                        I    DOF    DEALE
        CAUSE: Mouse free unit.
        CORRECTION: Unit mouse freed.

```

```

*****
Job # Part No   Description                PARTS   Bill to   Qty   Price   Total
*****
1      840821034507 12V 24 MDP BATTERY          I-PDI   1      95.88   95.88
3      82204500      4500 SUPER GLIDE FW HITC   I-DO    1      2,439.92 2,439.92
CIN    019079236326 TOILET TISSUE, SGL. 2 PL   I-PDI   1      1.02    1.02
CIN    014717396042 HTS STANDARD 10' SEWER H   I-PDI   1      7.46    7.46
CIN    019079900142 PARK ADAPTER BULK 30-15    I-PDI   1      2.33    2.33
CIN    093344312410 ADAPTER 30 AMP MALE TO 5   I-PDI   1      16.47   16.47
4      816456012029 CAPTURE PLATE RHINO PINB   I-DO    1      190.50  190.50
5      024098503021 EXTENSION CORD, 50A 30'   W-1020  0      180.66   0.00
MFP40 822051024     MOUSE FREE PRO 5 GALLON   I-DOF   40     4.50    180.00
WARR0 8220420064     TAIL LIGHT REFLECT RING   W-1020  1      3.20    3.20

```

```

*****
Job# Lab Code Description    LABOUR   Mech Bill to   Hrs   Rate   Total
*****
1 RV1F-3  SOLD COMPLETE PREP    CF   I-PDI   0.23  70.00  16.10
1 RV1F-3  SOLD COMPLETE PREP    CF   I-PDI   0.65  70.00  45.50
1 RV1F-3  SOLD COMPLETE PREP    CF   I-PDI   0.77  70.00  53.90
1 RV1F-3  SOLD COMPLETE PREP    CF   I-PDI   1.80  70.00  126.00
1 RV1F-3  SOLD COMPLETE PREP    CF   I-PDI   0.88  70.00  61.60
1 RV1F-3  SOLD COMPLETE PREP    CF   I-PDI   0.17  70.00  11.90
3 Z991    INSTALL FIFTH WHEEL HI RW   I-DO  1.50  70.00  105.00
ST RV1D-3 SHOW THRU & PICK UP PD CF   I-PDI   2.00  70.00  140.00
CIN CI     CLEAN INTERIOR          SL   I-PDI   3.47  70.00  242.90
CEN CE     CLEAN EXTERIOR          EJ   I-PDI   0.90  70.00  63.00
4 Z991    CAPTURE PLATE INSTALL    CF   I-DO    0.50  70.00  35.00

```

Continued on page 3

Work Order : 12172

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR CF  W-1020    0.00   140.00    0.00
ARR01 Z992      MISC LABOUR CODE (WARR CF  W-1020    0.05   140.00    7.00
ARR01 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.15   140.00   21.00
NFWS RV1F-1A    NEW STOCK PREP            TD  W-1020    0.25   140.00   35.00
MXGD Z991      APPLY MAXXGUARD TO UNI EJ  I-DOF    1.00    70.00   70.00
MFP40 Z991      INSTALL MOUSE FREE PRO TD  I-DOF    1.00    70.00   70.00
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to    Qty    Price    Total
*****
  1  LP      PROPANE            I-PDI    60.00    0.74   44.40
  3  FRT      FREIGHT FOR CAPTURE PLATE I-DO     0.00    0.00    0.00
ARR01 SSE      SHOP SUPPLIES - EXTERNAL W-1020    1.00    0.00    0.00
ARR01 FRT      FREIGHT FOR JOB WARR01   W-1020    0.00    0.00    0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I   DO            2630.42   140.00    0.00     0.00     0.00   2,770.42
I   DOF           180.00   140.00    0.00     0.00     0.00   320.00
I   PDI           123.16   760.90    0.00    44.40     0.00   928.46
W   1020           3.20     63.00    0.00     0.00     0.00    66.20

Totals          2936.78  1103.90    0.00    44.40     0.00  4,085.08
*****
```

&k2S
&k0S