

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 12173

|                 |                     |                 |                        |
|-----------------|---------------------|-----------------|------------------------|
| Date In:        | 06 JUN 25           | Author:         | MGRAY                  |
| Promised Date:  | 16 JUN 25           | Stock No:       | 10706                  |
| :               | :                   | Year:           | 2023                   |
| Customer Name:  | 1021 - FOREST RIVER | Manufacturer:   | FOREST RIVER           |
| Address:        | 21815 NETWORK PLACE | Brand:          | FLAGSTAFF E-PRO        |
| :               | CHICAGO, IL         | Model:          | E15TB                  |
| Postal/Zip:     | 60673-1218          | Miles/Hrs:      | 0                      |
| Phone#(res):    | 219-534-3167        | Exterior Color: |                        |
| Phone#(bus):    | 219-534-3167        | Unit Type:      | TT-TRAVEL TRAILER      |
| Cell Phone:     |                     | License#:       |                        |
| Email:          | NONE                | Tag#:           | ryan working on. accid |
| Purchased Date: | 16 AUG 24           | :               | :                      |
| Delivery Date:  | 23 AUG 24           | :               | :                      |
| InService Date: |                     | :               | :                      |
| Serial#:        | 5ZT2FSDC3P3027160   | :               | :                      |

\*\*\*\*\*

| Job # | Description | JOB INFORMATION                                                                                   | Type | Bill To    |
|-------|-------------|---------------------------------------------------------------------------------------------------|------|------------|
| WARR  | COMPLAINT:  | WARRANTY REPAIR 1 - shower miser is leaking. knob is not holding back water in bathroom           | W    | 1021 FORES |
|       | CAUSE:      | valve bad on the shower mise,                                                                     |      |            |
|       | CORRECTION: | replaced valve, tests well.                                                                       |      |            |
| WARR  | COMPLAINT:  | WARRANTY REPAIR 2 - cabinet doors need adjustment again as they are sagging.LEFT SIDE LOOKING IN. | W    | 1021 FORES |
|       | CAUSE:      | CABINET DOORS NEED ADJUSTMENT,                                                                    |      |            |
|       | CORRECTION: | ADJUSTED ALL CABINET DOORS, ALL TESTED WELL AFTER                                                 |      |            |

\*\*\*\*\*

| Job # | Part No  | Description                | PARTS | Bill to | Qty | Price | Total |
|-------|----------|----------------------------|-------|---------|-----|-------|-------|
| WARR0 | 82204417 | SHOWERMISER W/SHORT THREAD |       | W-1021  | 1   | 37.44 | 37.44 |

\*\*\*\*\*

| Job#  | Lab Code | Description               | LABOUR | Mech | Bill to | Hrs  | Rate   | Total |
|-------|----------|---------------------------|--------|------|---------|------|--------|-------|
| ARR01 | Z992     | MISC LABOUR CODE (WARR RW | W-1021 |      |         | 0.50 | 140.00 | 70.00 |
| ARR02 | Z992     | MISC LABOUR CODE (WARR RW | W-1021 |      |         | 0.50 | 140.00 | 70.00 |

\*\*\*\*\*

| BILLINGS SUMMARY |         |       |        |        |        |      |        |
|------------------|---------|-------|--------|--------|--------|------|--------|
| Type             | Bill Id | Parts | Labour | Sublet | Extras | Tax  | Total  |
| W                | 1021    | 37.44 | 140.00 | 0.00   | 0.00   | 9.77 | 187.21 |

Continued on page 2

Work Order : 12173

\*\*\*\*\*

## BILLINGS SUMMARY

| Type Bill Id | Parts | Labour | Sublet | Extras | Tax  | Total  |
|--------------|-------|--------|--------|--------|------|--------|
| *****        |       |        |        |        |      |        |
| Totals       | 37.44 | 140.00 | 0.00   | 0.00   | 9.77 | 187.21 |

&k2S  
&k0S