

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12205B

Date In: 22 SEP 25 Author: KOTT
Promised Date: 25 DEC 25 Stock No: 11319
: Year: 2025
Customer Name: 17594 - TRENT, JOHN Manufacturer: FOREST RIVER
Address: W9480 COUNTY RD S Brand: FLAGSTAFF CLASSIC FW
: NEW LONDON, WI Model: 374DBH
Postal/Zip: 54961 Miles/Hrs: 0
Phone#(res): 920-716-0643 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: JTRENT1@GMAIL.COM Tag#: DB: 09/22/2025
Purchased Date: 17 JAN 25 :
Delivery Date: 01 MAY 25 :
InService Date: :
Serial#: 4X4FFLN22S1908672 :

Job # Description JOB INFORMATION Type Bill To

9 COMPLAINT: CUSTOMER STATES THAT THE OVEN DOES NOT W 1021 FORES
WORK PROPERLY- CUSTOMER STATES THAT THE
OVEN WILL LIGHT FOR ABOUT 2 MINUTES THEN
IT WILL CUT OFF-
CAUSE: When running the oven, pilot light comes
on, then burner ignights. It will run
for a short time and then kicks out
shutting off gas pressure. According to
thermometer, ot is kicking out at 200F
submit to warranty for replacement.
CORRECTION: ... REQUEST 1.5 HOURS OF LABOR
10 COMPLAINT: CUSTOMER STATES THAT THE SCREENS IN THE W 1021 FORES
WINDOWS DO NOT FIT TIGHT-
CAUSE: Screens complaint. All of them? States
the screens dont fit tight. Inspected
screens in coach, they appear to be
fitting as they should. Removed and
refit bedroom screens, seems alright to
me.
CORRECTION: The gap between the screen and
windowframe measures less than 1/16" NPF
request .15 hours of labor
11 COMPLAINT: IN BATHROOM WHERE IT IS CAULKED THERE IS W 1021 FORES
A BLACK SPOT IN THE WHITE SEALANT, CAN
WE CORRECT THAT.
CAUSE: Black foam poking out of white silicon,
repaired it while clocked into other
line for shower.

Continued on page 2

Work Order : 12205B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CORRECTION: Removed section of sealant. Cleaned
area, resealed.  REQUEST .30 HOURS OF
LABOR
12      COMPLAINT:  IN THE SHOWER THERE IS CAULK THAT IS ON  W    1021  FORES
THE WALL, LIKE IT WAS APPLIED SLOPPY BE
MANUFATUERER
CAUSE:    Sloppy workmanship at production. Needs
some clean up effort. Cosmetic
CORRECTION: Removed section of silicon, cleaned with
a solvent, and resealed. Looks more
appealing now.  REQUEST 1 HOUR OF LABOR
13      COMPLAINT:  IN THE MAIN LIVING AREA THERE IS TRIM    W    1021  FORES
COMING LOOSE.
CAUSE:    Could not find loose trim in living
area, only tape mark was next to a putty
discrepancy.
CORRECTION: Fixed putty mishap.  REQUEST .20 HOURS
OF LABOR
14      COMPLAINT:  BTHROOM DOOR OPENING ONE OF THE TRIM    W    1021  FORES
PIECES ARE BOWED, CAN WE FIX AND GET
PINNED BACK DOWN.
CAUSE:    Trim piece bowed in a few spots.
CORRECTION: Glued and applied pressure overnight to
questionable trim piece. Did two rounds
of glue and pressure. Outside corner
trim looks fine again.  REQUEST .60
HOURS OF LABOR
15      COMPLAINT:  THERE IS SOME CAULKING MISSING ON THE    W    1021  FORES
COUNTER TOP WHERE IT GOES FROM LOWER TO
HIGHER
CAUSE:    Missing calking.
CORRECTION: Used white nova-flex to fill in the gap.
REQUEST .2 HOURS OF LABOR
16      TOP OFF LP
17      COMPLAINT:  ODS FRONT COMPARTMENT WITH LEVELING    E    17594  TRENT
SYSTEM, THE SCREEN IN THE PANEL IS
UNATTACHD AND FREE FLOATING IN PANEL.
CHECK OUT FOR REPAIR, REPLACE.
CAUSE:    Looks like the screen detached inside of
the leveling control.
CORRECTION: One side of the control board was
dislodged from the clips holding it in
place. Reclipped, seemed to stay in place
fine. Reattached, working fine.
REQUEST .30 HOURS OF LABOR

```

Continued on page 3

Work Order : 12205B

```
*****
Job # Part No Description      PARTS      Bill to  Qty    Price    Total
*****
14    146877  NOVAFLEX SEALANT WHITE      W-1021    1    11.93    11.93
*****
```

```
*****
Job#  Lab Code Description      LABOUR    Mech Bill to    Hrs    Rate    Total
*****
  9  Z992      MISC LABOUR CODE (WARR RW  W-1021    0.46  140.00    64.40
  9  Z992      MISC LABOUR CODE (WARR RW  W-1021    0.04  140.00     5.60
 10  Z992      MISC LABOUR CODE (WARR RW  W-1021    0.50  140.00    70.00
 11  Z992      MISC LABOUR CODE (WARR RW  W-1021    0.50  140.00    70.00
 12  Z992      MISC LABOUR CODE (WARR RW  W-1021    0.50  140.00    70.00
 13  Z992      MISC LABOUR CODE (WARR RW  W-1021    0.50  140.00    70.00
 14  Z992      MISC LABOUR CODE (WARR RW  W-1021    0.08  140.00    11.20
 14  Z992      MISC LABOUR CODE (WARR RW  W-1021    0.18  140.00    25.20
 14  Z992      MISC LABOUR CODE (WARR RW  W-1021    0.24  140.00    33.60
 15  Z992      MISC LABOUR CODE (WARR RW  W-1021    0.50  140.00    70.00
 17  Z992      MISC LABOUR CODE (WARR RW  W-1021    0.50  140.00    70.00
*****
```

```
*****
Job #  Excode  Description      EXTRAS      bill to  Qty    Price    Total
*****
  13  SSE      SHOP SUPPLIES - EXTERNAL  W-1021    1.00    0.00    0.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1021      11.93    560.00    0.00    0.00    0.00    571.93
      Totals    11.93    560.00    0.00    0.00    0.00    571.93
*****
```

&k2S
&k0S