

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12217

Date In: 14 JUN 25 Author: MGRAY
Promised Date: 31 DEC 25 Stock No: 11424
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN
Address: 8220 STATE HWY 13 SOUT Brand: SOLITUDE
: WISCONSIN RAPIDS, WI Model: 310GK
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: NONE Tag#: DB: 8/6
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573FS3621SAA21933 :

```
*****  
Job # Description JOB INFORMATION Type Bill To  
*****  
CEN CLEAN EXTERIOR- NEW I PDI PRE-D  
NFWS COMPLAINT: NEW FIFTH WHEEL STOCK PREP I PDI PRE-D  
CAUSE: New unit prep  
CORRECTION: Complete prep done  
1 COMPLAINT: FOUND WHILE TRANSFERING THE FURNITURE W 1020 GRAND  
FOUND THAT THE CONVERTOR IS NOT PUTTING  
OUT ANY POWER-  
CAUSE: Check converter for operation. Not  
getting 12 volts.  
CORRECTION: Found that both fuses were blown .  
Installed 2 new fuses. Tested good. REQ  
.30 HOURS OF LABOR WARRANTY AUTH: .20  
HOURS  
WARR COMPLAINT: WARRANTY REPAIR 1 - the fresh waters W 1020 GRAND  
pull valve will not close I try filling  
tank and water comes out and handle does  
not push in  
CAUSE: Improper install the clamp that holds  
the valve stem in place is way off to  
the side  
CORRECTION: Moved clamp over so the rod pushes in  
straight REQ .10 HOURS OF LABOR WARR  
AUTH: .20  
WARR COMPLAINT: WARRANTY REPAIR 2 - dicor needed on d W 1020 GRAND  
few spots on the roof  
CAUSE: Mfg  
CORRECTION: Cleaned then sealed REQEUST .50 HOURS  
OF LABOR WARR AUTH .50
```

Continued on page 2

Work Order : 12217

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 3 -kitchen faucet all of W   1020   GRAND
        CAUSE:      Broken piece inside the faucet head I
                    removed the faucet head and looked for
                    debris nothing but the plastic plunger
                    seems to be sticking and not allowing
                    water through it works for a bit then I
                    hear d snap sound dnd water quits
                    running through the head but comes out
                    of hose the head is attached to so it is
                    a faulty spray head PLEASE ORDER NEW
                    Kitchen FAUCET HEAD Took a while to
                    retrieve unit from lot, slides required
                    a battery.      Kitchen faucet
                    replacement per warranty.
        CORRECTION:  .... Replaced and tested kitchen
                    faucet, working well now.      The cutting
                    board is missing from sink.

```

```

*****
Job # Part No Description      PARTS      Bill to Qty Price Total
*****
WARR0 82200578 FAUCET BLACK FOR 27" RAINFAL W-1020      1      87.75 87.75

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
CEN CE CLEAN EXTERIOR I-PDI 0.00 70.00 0.00
NFWS RV1F-1A NEW STOCK PREP HOD I-PDI 1.09 70.00 76.30
1 WARR MANUFACTURER WARRANTY TD W-1020 0.20 140.00 28.00
NFWS RV1F-1A NEW STOCK PREP HOD I-PDI 1.51 70.00 105.70
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.20 140.00 28.00
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.50 140.00 70.00
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.13 140.00 18.20
NFWS RV1F-1A NEW STOCK PREP HOD I-PDI 0.08 70.00 5.60
NFWS RV1F-1A NEW STOCK PREP HOD I-PDI 1.70 70.00 119.00
NFWS RV1F-1A NEW STOCK PREP HOD I-PDI 0.12 70.00 8.40
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.00 140.00 0.00
ARR03 WARR MANUFACTURER WARRANTY RW W-1020 0.00 140.00 0.00
ARR03 WARR MANUFACTURER WARRANTY RW W-1020 0.62 140.00 86.80

```

```

*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1020 1.00 0.00 0.00
ARR03 FRT FREIGHT FOR WARRANTY LINE W-1020 1.00 25.09 25.09

```

Continued on page 3

Work Order : 12217

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	PDI	0.00	315.00	0.00	0.00	0.00	315.00
W	1020	87.75	231.00	0.00	25.09	0.00	343.84
	Totals	87.75	546.00	0.00	25.09	0.00	658.84

&k2S
&k0S