

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12235

Date In:	17 JUN 25	Author:	MGRAY
Promised Date:	31 DEC 25	Stock No:	11410
:	:	Year:	2026
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	PUMA TT
:	WISCONSIN RAPIDS, WI	Model:	337BH
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	5ZT2PUZB2T4024554	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CEN     COMPLAINT:  CLEAN EXTERIOR- NEW                                I      PDI      PRE-D
        CAUSE:      NEED CLEAN
        CORRECTION:  CLEANED
NTTS    COMPLAINT:  NEW TRAVEL TRAILER STOCK PREP                    I      PDI      PRE-D
        CAUSE:      Done
        CORRECTION:  Done
WS      COMPLAINT:  WINTERIZE WATER SYSTEM & TRAPS -SELF            I      PDI      PRE-D
        CAUSE:      Done
        CORRECTION:  Done
WARR    COMPLAINT:  Transferred to GRV*12235B on 01 DEC 25          W      1021     FORES
        Estimate amount was 0.00 WARRANTY REPAIR
        1 - the rear bottom corners are not
        fully sealed up as well as the rear
        slide track is missing silicone.
        CAUSE:      The slide track on the rear on the slide
        had seperated from the wall so i sealed
        that up with silicone and then both rear
        bottom corners had seperated from the
        trim i also sealed that with silicone
        CORRECTION:  Done
WARR    COMPLAINT:  Transferred to GRV*12235B on 01 DEC 25          W      1021     FORES
        Estimate amount was 0.00 WARRANTY REPAIR
        2 - the rubber seal on the top right of
        the ods bunk room closet is not applied
        properly and is all bunched up
        CAUSE:      The rubber seal along the edge inside
        the ods bunk closet was tucked into the
```

Continued on page 2

Work Order : 12235

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                wall and i couldnt pull it out without
                                ripping it so i covered it with a baton
                                strip
CORRECTION: Done.

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WS      009114950003 -50 F GLYCERIN FREE BASE I-PDI      3      6.62      19.86
NTTS    8220BG24      GROUP 24 BATTERY BOX SNA I-PDI      1      10.36      10.36

```

```

*****
Job#   Lab Code   Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
CEN CE      CLEAN EXTERIOR      EG      I-PDI      0.83      70.00      58.10
NTTS RV1F-1A NEW STOCK PREP      EG      I-PDI      1.17      70.00      81.90
WS W495      WINTERIZE RV (WATER SY EG      I-PDI      0.70      70.00      49.00
NTTS RV1F-1A NEW STOCK PREP      EG      I-PDI      0.91      70.00      63.70
NTTS RV1F-1A NEW STOCK PREP      EG      I-PDI      0.49      70.00      34.30
NTTS RV1F-1A NEW STOCK PREP      EG      I-PDI      0.65      70.00      45.50
NTTS RV1F-1A NEW STOCK PREP      EG      I-PDI      0.52      70.00      36.40
NTTS RV1F-1A NEW STOCK PREP      EG      I-PDI      0.76      70.00      53.20
ARR01 Z992      MISC LABOUR CODE (WARR EG      W-1021      0.00      140.00      0.00
ARR02 Z992      MISC LABOUR CODE (WARR EG      W-1021      0.00      140.00      0.00

```

```

*****
Job #   Excode   Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR01   SSE      SHOP SUPPLIES - EXTERNAL      W-1021      0.00      0.00      0.00

```

```

*****
BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I      PDI      30.22      422.10      0.00      0.00      0.00      452.32

Totals      30.22      422.10      0.00      0.00      0.00      452.32

```

&k2S
&k0S