

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12240

Date In: 18 JUN 25 Author: DLUCAS
Promised Date: 31 DEC 25 Stock No: 11167
: Year: 2024
Customer Name: 16584 - PETRILLO, VERO Manufacturer: FOREST RIVER
Address: 7840 KOLMAR AVENUE Brand: PUMA DESTINATION
: SKOKIE, IL Model: 402LFT
Postal/Zip: 60076 Miles/Hrs: 0
Phone#(res): 847-334-7937 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: RASPREIT@GMAIL.COM Tag#: DB:7/2
Purchased Date: 28 JUN 24 :
Delivery Date: 11 JUL 24 :
InService Date: :
Serial#: 4X4TPUS26RP102822 :

Job # Description JOB INFORMATION Type Bill To

| | | | | | |
|----|--|---|------|-------|-------|
| SC | CUSTOMER REQUESTS A SERVICE CALL TO THEIR UNIT: 32335 CTY RD G WOULD LIKE FREE SERVICE CALL *NEED FREE SERVICE CALL VOUCHER TO HONOR* OXFORD, WI DID NOT SUPPLY VOUCHER AS OF YET.. | | E | 16584 | PETRI |
| 1 | COMPLAINT: AWNING GOES OUT BUT WILL NOT COME BACK IN ALL THE WAY, COMES IN A BIT BUT STOPS AND CANT GET IT IN WOULD LIKE ADDRESSED CAUSE: pics taken of parts used I checked voltage at awning switch 13.52 and checked voltage at motor was 13.51 I diagnose motor awning motor weak it extend and retracted but just slow retracting this is a really long awning CORRECTION: replaced the awning motor and awning switch I tested awning it extend and retracted slowly due to how long awning is APPROVED .50 HOURS OF LABOR | W | 1021 | FORES | |
| 2 | COMPLAINT: CUSTOMER STATES SHADE IN HALLWAY NOT GOING UP WOULD LIKE LOOKED AT CAUSE: Will need new shade when it rolls up it all goes to one side CORRECTION: Will need a new shade for hallway.... WARRANTY AUTH: .20 HOURS | W | 1021 | FORES | |
| 3 | COMPLAINT: CUSTOMER STATES WALLPAPER AROUND WINDOWS IN A FEW SPOTS, WOULD LIKE TO MAKE SURE ITS NATURAL AND NOT WATER DAMAGED CAUSE: wall paper wrinkles around window frame work I had removed framework from one | W | 1021 | FORES | |

Continued on page 2

Work Order : 12240

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
window and shown customer it's not water
damage I had enough seam tape to do one
window will need more seam tape and
about will need about 3 more hours to do
5 more windows Put seam tape around
windows that have wrinkles by the trim
ring.
CORRECTION: Will need approval to do 5 more window
i figure 3 hours to cut out wrinkles
around window and seam tape .... Seam
taped windows that needed it. WARRANT
AUTH: 3.60 HOURS OF LABOR
WS      WINTERIZE WATER SYSTEM & TRAPS -SELF CONTAINED -      E      16584  PETRI
TOWABLE

```

```

*****
Job # Part No      Description          PARTS      Bill to      Qty      Price      Total
*****
1      154328          REPLACEMENT AWNING MOTOR W-1021          1      451.20      451.20
2      82205364        SHADE ROLLER 27X72 BAMBO W-1021          1      54.59      54.59
3      F100347337      SEAM TAPE, 1", CLOUDED T W-1021          1      0.16      0.16
WS     071247312003  -50 ANTIFREEZE/ 1 GALLON E-16584          3      9.62      28.86

```

```

*****
Job# Lab Code Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
1 WARR      MANUFACTURER WARRANTY JS W-1021          1.70      140.00      238.00
2 WARR      MANUFACTURER WARRANTY JS W-1021          0.50      140.00      70.00
3 WARR      MANUFACTURER WARRANTY JS W-1021          1.10      140.00      154.00
2 WARR      MANUFACTURER WARRANTY TD W-1021          0.00      140.00      0.00
3 WARR      MANUFACTURER WARRANTY TD W-1021          2.50      140.00      350.00
3 WARR      MANUFACTURER WARRANTY W-1021          0.00      140.00      0.00
WS W495      WINTERIZE RV (WATER SY TD E-16584          0.70      130.00      91.00
2 WARR      MANUFACTURER WARRANTY TD W-1021          0.08      140.00      11.20
3 WARR      MANUFACTURER WARRANTY TD W-1021          0.00      140.00      0.00

```

```

*****
Job # Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
SC SSE          SHOP SUPPLIES - EXTERNAL E-16584          1.00      6.83      6.83
SC SC          SERVICE CALL          E-16584          33.00      3.75      123.75
SC SC          SERVICE CALL          E-16584          33.00      3.75      123.75
2 FRT          FREIGHT FOR JOB 2          W-1021          1.00      39.07      39.07
3 FRT          FREIGHT          W-1021          1.00      18.81      18.81
WS J-ADJ        QUOTE ADJUSTMENT          E-16584          1.00      -14.86      -14.86

```

Continued on page 3

Work Order : 12240

BILLINGS SUMMARY

| Type | Bill Id | Parts | Labour | Sublet | Extras | Tax | Total |
|------|---------|--------|--------|--------|--------|-------|----------|
| E | 16584 | 28.86 | 91.00 | 0.00 | 239.47 | 19.79 | 379.12 |
| W | 1021 | 505.95 | 823.20 | 0.00 | 57.88 | 0.00 | 1,387.03 |
| | Totals | 534.81 | 914.20 | 0.00 | 297.35 | 19.79 | 1,766.15 |

&k2S
&k0S