

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12261B

Date In:	30 JUN 25	Author:	KOTT
Promised Date:	28 JUN 25	Stock No:	11259
:	:	Year:	2025
Customer Name:	122926 - MCDONOUGH, MI	Manufacturer:	FOREST RIVER
Address:	1148 S. BUTTERCUP CT.	Brand:	PUMA DESTINATION
:	FRIENDSHIP, WI	Model:	402LFT
Postal/Zip:	53934	Miles/Hrs:	0
Phone#(res):	262-939-5796	Exterior Color:	
Phone#(bus):		Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:	YMIKEJ@YAHOO.COM	Tag#:	PU@ST- 6/28@830
Purchased Date:	21 JUN 25	:	:
Delivery Date:	28 JUN 25	:	:
InService Date:		:	:
Serial#:	4X4TPUS2XSP104319	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
2-1     COMPLAINT:  BOTTOM DRAWER ON THE ISLAND IN THE           W    1021    FORES
        KITCHEN CLOSES ROUGH/NEEDS TO BE FORCED
        CAUSE:       Mfg installed the whole drawer system
                    wrong
        CORRECTION:  Removed the way to wide of boards
                    holding frame for glides to be installed
                    on reason to wide drawers could not
                    close all of the way cut 3 thinner
                    pieces of wood and installed bottom
                    drawer closes great but now the
                    REQUEST 1 HOUR OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 1 - catch for cabinet       W    1021    FORES
        door is loose
        CAUSE:       Improper install
        CORRECTION:  I removed the one screw at bottom of
                    catch that was holding it to the frame
                    of cabinet barely then used longer
                    screws to secure the bracket in place
                    and opened and closed the door for
                    proper operation it catch's as it should
                    and not difficult to pull open  REQUEST
                    .30 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 3 - the black steps         W    1021    FORES
        going up to loft area have scratches in
        the finish
        CAUSE:       Mfg scratched the finish while install
        CORRECTION:  I used a black paint pen to cover the
                    numerous scratches in black finish
```

Continued on page 2

Work Order : 12261B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  REQUEST .40 HOURS OF LABOR
          WARRANTY REPAIR 4 - Mark on wall going   W    1021   FORES
          upstairs
          CAUSE:    Pen Marks on wall mfg
          CORRECTION: Tried cleaning it did lighten the marks
                      then I used s crayon to cover the
                      remaining visable marks  REQUEST .20
                      HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 6 -To the left of   W    1021   FORES
          bathroom sink the cabinetry face does
          not lay flat all of the way down to the
          floor gap gets wider going down like
          face is warped a bit ,it is not loose
          CAUSE:    Warped cabinet faces
          CORRECTION: I used white silicone to fill the gaps
                      between the wall and face of cabinets on
                      each side of shower stall  REQUEST .75
                      HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 7 -Some pull down shades W    1021   FORES
          have strings loose on the edges
          CAUSE:    Loose strings
          CORRECTION: I carefully burned away loose strings
                      they no longer can unravel  REQUEST .30
                      HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 8 - Carpeting going   W    1021   FORES
          upstairs has strings from edges
          CAUSE:    Loose strings from edges of carpeting
                      left by mfg
          CORRECTION: I cut away the strings  REQUEST .30
                      HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 9 - DS slide the   W    1021   FORES
          eternabond tape is beginning to lift at
          back edge
          CAUSE:    Mfg may not have cleaned fabric on roof
                      good enough and tape did not stay down
          CORRECTION: Cleaned area well removed 3 screws from
                      top screw trim pulled it away from
                      fabric then installed eterna bond tape
                      over the edge of the peeled tape and
                      beneath screw trim then reinstalled trim
                      and silicone top of the trim  REQUEST
                      .50 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 11 - Shower base on   W    1021   FORES
          outside has a gap between wall and base
          CAUSE:    Gap
          CORRECTION: Used white silicone to fill the gap
                      REQUEST .40 HOURS OF LABOR

```

Continued on page 3

Work Order : 12261B

```
*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 146880      NOVAFLEX SEALANT CANVAS      W-1021      1      7.87      7.87
WARR0 891991000533 ETERNABOND WHITE      W-1021      2      1.86      3.72
WARR1 146877      NOVAFLEX SEALANT WHITE      W-1021      1      7.87      7.87
*****
```

```
*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
  2-1 WARR      MANUFACTURER WARRANTY      HOD      W-1021      0.50      140.00      70.00
ARR01 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.50      140.00      70.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.11      140.00      15.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.06      140.00      8.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.33      140.00      46.20
ARR04 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.41      140.00      57.40
ARR04 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.01      140.00      1.40
ARR04 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.08      140.00      11.20
ARR06 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.49      140.00      68.60
ARR06 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.01      140.00      1.40
ARR07 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.48      140.00      67.20
ARR07 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.02      140.00      2.80
ARR08 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.47      140.00      65.80
ARR08 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.03      140.00      4.20
ARR09 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.50      140.00      70.00
ARR09 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.00      140.00      0.00
ARR11 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.49      140.00      68.60
ARR11 Z992      MISC LABOUR CODE (WARR HOD      W-1021      0.01      140.00      1.40
*****
```

```
*****
Job #  Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL      W-1021      1.00      0.00      0.00
*****
```

```
*****
BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      19.46      630.00      0.00      0.00      0.00      649.46
*****
Totals      19.46      630.00      0.00      0.00      0.00      649.46
*****
```

&k2S

&k0S