

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12272B

Date In: 10 JUL 25 Author: KOTT
Promised Date: 25 DEC 25 Stock No: 11333
: Year: 2026
Customer Name: 17752 - KRAUTER, JOSHU Manufacturer: FOREST RIVER
Address: 7380 JEANELLEN ROAD Brand: PUMA DESTINATION
: WEST BEND, WI Model: 402LFT
Postal/Zip: 53090 Miles/Hrs: 0
Phone#(res): 4143775800 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: DB:7/11
Purchased Date: 21 JUN 25 :
Delivery Date: 11 JUL 25 :
InService Date: :
Serial#: 4X4TPUS27TP106367 :

```
*****
Job # Description JOB INFORMATION Type Bill To
*****
WARR COMPLAINT: WARRANTY REPAIR 1 - the drawer guide the W 1021 FORES
bearings came out when opening the
drawer
CAUSE: Ball bearings fell out from mfg I cut
the guide that goes to side of drawer
then installed new rail and guide to
side of drawer but to no avail need new
drawer with new guides installed on each
side and new rails on each side drawer
has damage to the inside wood which is
not able to be repaired. ORDER NEW
DRAWER WITH GUIDES INSTALLED ON SIDES
AND NEW GLIDES FOR EACH SIDE DRAWER
MEASURES 12 1/4" wide x 13 3/4" deep the
face is 13 3/4 " x 6" tall pics of
everything taken
CORRECTION: ..... request .50 hours of labor

WARR COMPLAINT: WARRANTY REPAIR 2 - the screen door is W 1021 FORES
way to bent for installation tried and
the top metal of door keeps separating
CAUSE: Mfg using very Subpar screen doors for
patio doors PLEASE ORDER NEW BLACK
SLIDING SCREEN DOOR 30" WIDE X 72"TALL
CORRECTION: ..... req .20 hours of labor

WARR COMPLAINT: WARRANTY REPAIR 3 - the gutter is W 1021 FORES
leaking down onto the speaker door side
CAUSE: Mfg did not seal it well
```

Continued on page 2

Work Order : 12272B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CORRECTION: Used black silicone to seal the crack
            request .30 hours of labor

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE     SHOP SUPPLIES - EXTERNAL  W-1021  1.00  0.00  0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W  1021      0.00  210.00  0.00  0.00  0.00  210.00
Totals      0.00  210.00  0.00  0.00  0.00  210.00

```

&k2S
&k0S