



<b>Model #</b>		<b>Serial #</b>		<b>Part tag</b>	
Sub Qty	1.00	Sub Dlr Price	\$53.13	Sub Freight	\$164.34
Appr Qty	1.00	Appr Dlr Price	\$53.13	Appr Freight	\$164.34

**Notes**

**Line# 2**

<b>Item #</b>		<b>Description</b>		<b>Part tag</b>	
420-C		CRATING			
<b>Model #</b>		<b>Serial #</b>		<b>Part tag</b>	
Sub Qty	1.00	Sub Dlr Price	\$52.00	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$0.00	Appr Freight	\$40.00

**Notes**

**Labor**

**Line# 3**

<b>Operation Code</b>	<b>Operational Description</b>
20-43-19-00-001109	Gutter Rail - Exterior/Exterior Miscellaneous/Reseal/No Tread Code
<b>Complaint, Cause, Correction</b>	
Original Note : greenway@dealer-advisors.com, 2026-04-07 08:34:46 :: Complaint: The gutter is leaking down onto the speaker on the door side. Cause: Manufacturer did not seal well. Correction: Used black silicone to seal the crack.	

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$28.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$28.00

**Notes**

**Part**

**Line# 1**

<b>Item #</b>		<b>Description</b>		<b>Part tag</b>	
USERPART		shop supplies - sealant			
<b>Model #</b>		<b>Serial #</b>		<b>Part tag</b>	
Sub Qty	1.00	Sub Dlr Price	\$1.40	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$1.40	Appr Freight	\$0.00

**Notes**

<b>Submitted</b>	Labor Amt	\$84.00	<b>Approved</b>	Labor Amt	\$84.00
	Parts & Freight	\$314.70		Parts & Freight	\$302.70
	Total	\$398.70		Total	\$386.70

\_\_\_\_\_  
**DEALER** **DATE**  
**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

\_\_\_\_\_  
**CUSTOMER** **DATE**  
**SIGNATURE**

All repairs described have been inspected and are satisfactory.