

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12276

Date In: 25 JUN 25 Author: MGRAY
Promised Date: 31 DEC 25 Stock No: 11435
: Year: 2026
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT Brand: FLAGSTAFF MICRO-LITE
: WISCONSIN RAPIDS, WI Model: 25MBR
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#:
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 4X4TFLB20TZ198245 :

Job # Description JOB INFORMATION Type Bill To

CEN COMPLAINT: CLEAN EXTERIOR- NEW I PDI PRE-D
CAUSE: New unit
CORRECTION: Washed for lot
NTTS COMPLAINT: NEW TRAVEL TRAILER STOCK PREP I PDI PRE-D
CAUSE: New unit
CORRECTION: Done
WARR COMPLAINT: WARRANTY REPAIR 1 -magnets for front W 1021 FORES
shade do not hold the shade as it should
they do not hold it at all
CAUSE: Magnetic hold is finicky
CORRECTION: I had Jesse come in and if you place it
just right it holds. I want this noted
in case future customer would like more
magnets so it's not so finicky to get
the shade to hold REQUEST: .50 HOURS OF
LABOR
WARR COMPLAINT: WARRANTY REPAIR 2 floor covering in W 1021 FORES
front of reclining chairs has stains
CAUSE: Stains from mfg
CORRECTION: Used solvent to clean away stains on
floor covering REQUEST .30 HOURS OF
LABOR
WARR COMPLAINT: WARRANTY REPAIR 3 - door header that is W 1021 FORES
between bedroom and kitchen is peeling
CAUSE: Chipped peeling finish mfg
CORRECTION: I used putty to cover the peeling edge
of finish REQUEST .15 HOURS OF LABOR
WARR COMPLAINT: WARRANTY REPAIR 4 - bottom edge of W 1021 FORES

Continued on page 2

Work Order : 12276

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
          bathroom countertop is rough
    CAUSE:   Rough cut bottom of countertop in
              bathroom
    CORRECTION: Used sandpaper and sanded down the rough
                areas it is now consistent and smooth
                along the bottom  REQUEST .15 HOURS OF
                LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 5 - above recliners the  W    1021    FORES
              end of ceiling trim is crooked and rough
              cut
    CAUSE:   Rough cut of trim from mfg
    CORRECTION: I sanded the end so no jagged pieces
                hanging down then cleaned the trim
                REQUEST .15 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 6 - trim in corner of    W    1021    FORES
              bedroom is cracked
    CAUSE:   Cracked trim
    CORRECTION: I used a bit of white putty to cover the
                crack in the trim  REQUEST .10 HOURS OF
                LABOR

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
  CEN CE      CLEAN EXTERIOR      HOD  I-PDI      0.63  70.00  44.10
  NTTS RV1F-1A  NEW STOCK PREP      HOD  I-PDI      0.63  70.00  44.10
  NTTS RV1F-1A  NEW STOCK PREP      HOD  I-PDI      0.01  70.00   0.70
ARR01 Z992     MISC LABOUR CODE (WARR HOD  W-1021    0.50  140.00  70.00
ARR02 Z992     MISC LABOUR CODE (WARR HOD  W-1021    0.50  140.00  70.00
ARR03 Z992     MISC LABOUR CODE (WARR HOD  W-1021    0.50  140.00  70.00
ARR04 Z992     MISC LABOUR CODE (WARR HOD  W-1021    0.50  140.00  70.00
ARR05 Z992     MISC LABOUR CODE (WARR HOD  W-1021    0.50  140.00  70.00
ARR06 Z992     MISC LABOUR CODE (WARR HOD  W-1021    0.50  140.00  70.00
  NTTS RV1F-1A  NEW STOCK PREP      HOD  I-PDI      2.57  70.00  179.90
  NTTS RV1F-1A  NEW STOCK PREP      HOD  I-PDI      1.29  70.00   90.30

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE     SHOP SUPPLIES - EXTERNAL  W-1021  1.00  0.00  0.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
I    PDI          0.00   359.10   0.00   0.00   0.00  359.10
W    1021         0.00   420.00   0.00   0.00   0.00  420.00

```

Continued on page 3

Work Order : 12276

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	0.00	779.10	0.00	0.00	0.00	779.10

&k2S
&k0S