

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 12291B

|                 |                        |                 |                   |
|-----------------|------------------------|-----------------|-------------------|
| Date In:        | 17 JUL 25              | Author:         | KOTT              |
| Promised Date:  | 31 DEC 25              | Stock No:       | 11408             |
| :               | :                      | Year:           | 2026              |
| Customer Name:  | 12979 - BURANT, MARIA  | Manufacturer:   | FOREST RIVER      |
| Address:        | 1546 ARBOR CREEK DRIVE | Brand:          | PUMA DESTINATION  |
| :               | OAK CREEK, WI          | Model:          | 403LFT            |
| Postal/Zip:     | 53154                  | Miles/Hrs:      | 0                 |
| Phone#(res):    | 414-507-8219           | Exterior Color: | :                 |
| Phone#(bus):    | :                      | Unit Type:      | TT-TRAVEL TRAILER |
| Cell Phone:     | :                      | License#:       | :                 |
| Email:          | :                      | Tag#:           | :                 |
| Purchased Date: | 11 JUN 25              | :               | :                 |
| Delivery Date:  | 15 JUL 25              | :               | :                 |
| InService Date: | :                      | :               | :                 |
| Serial#:        | 4X4TPUS22TP106390      | :               | :                 |

\*\*\*\*\*

| Job # | Description                                                                                 | JOB INFORMATION | Type | Bill To |
|-------|---------------------------------------------------------------------------------------------|-----------------|------|---------|
| WARR  | COMPLAINT: WARRANTY REPAIR 1 -the roof has sealant gaps                                     | W               | 1021 | FORES   |
|       | CAUSE: Gaps in roof sealant                                                                 |                 |      |         |
|       | CORRECTION: Cleaned areas well then dicored over the spots REQUEST .30 HOURS OF LABOR       |                 |      |         |
| WARR  | COMPLAINT: WARRANTY REPAIR 3 -bulb seal on the off door side rear slide out is coming off   | W               | 1021 | FORES   |
|       | CAUSE: Mfg loose bulb seal                                                                  |                 |      |         |
|       | CORRECTION: Removed seal then reinstalled and secured with screw REQUEST .20 HOURS OF LABOR |                 |      |         |
| WARR  | COMPLAINT: WARRANTY REPAIR 4 - windows have silicone smeared on windows                     | W               | 1021 | FORES   |
|       | CAUSE: Mfg left silicone on windows                                                         |                 |      |         |
|       | CORRECTION: Cleaned away with quick solve REQUEST .50 HOURS OF LABOR                        |                 |      |         |

\*\*\*\*\*

| Job#  | Lab Code | Description                | LABOUR | Mech | Bill to | Hrs   | Rate | Total |
|-------|----------|----------------------------|--------|------|---------|-------|------|-------|
| ARR01 | Z992     | MISC LABOUR CODE (WARR HOD | W-1021 | 0.50 | 140.00  | 70.00 |      |       |
| ARR03 | Z992     | MISC LABOUR CODE (WARR HOD | W-1021 | 0.50 | 140.00  | 70.00 |      |       |
| ARR04 | Z992     | MISC LABOUR CODE (WARR HOD | W-1021 | 0.13 | 140.00  | 18.20 |      |       |
| ARR04 | Z992     | MISC LABOUR CODE (WARR HOD | W-1021 | 0.37 | 140.00  | 51.80 |      |       |

Continued on page 2

Work Order : 12291B

```
*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021    1.00    0.00     0.00
*****
```

```
*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
W      1021        0.00     210.00     0.00     0.00     0.00     210.00

      Totals      0.00     210.00     0.00     0.00     0.00     210.00
*****
```

&k2S  
&k0S